

REPORT of SURVEY for REPAIRS.

Rec 16/10/72

No. in Reg. Book. **No 23453** Survey held at Liverpool Date, first Survey 27th Aug Last Survey 4th Sept 1872
 on the Iron S. "BARODA" Master J. Tully 94 ey/
 Tonnage 1364 built at Belfast When built 1864 - 4 mo
 By whom built Kearney Owners Brocklebank
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Clearance dry dock & Afloat
 Last Survey, No. 8730 Port Iron Classified *A 1
S.S. No 1.68 71

REPAIRS, &c.

Periodical Survey No 2

Feeling equal to 4 strakes each side lifted. Cement floors frames &c good. cleaned and painted - Chain Cables hauled up and ranged on deck - Windlass lumps stripped and Ends exposed & frame good. 6 planks of Deck near of Main Rudder pintles "bushed"

Present Condition of the

Decks	Greenails	Rivets	Windlass and Capstan	Good
Waterways	Breasthooks and Stemson		Pumps	2 ho
Comings	Transoms, Pointers, and Crutches		Boats	4 ho
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	Ditto Ditto at other places		Condition, how ascertained	
Planksheers	Keelsons		Sails	
Sheerstrakes	Clamps and Shelves		Anchors No. of	3 B. 15 & 2 K
Topsides	Ceiling		Cables	315 fms
Wales	Rudder		Hawsers and Warps	3 ho
Plank (Bottom) and Counter	Copper Cement When put on	1864	Standing & Running Rigging	
Engine Room Skylights	Caulking of		Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Good	Hatches	Good
Scuppers				

General Observations and Opinion,

She is now in good condition and in my opinion may remain as classed and marked S.S. No 2. 72

The Amount of Entry Fee.....£ " : " : " is received by me,

Special..... 3 : 3 : — 15/10/72

Certificate (if required) " : " : "

Committee's Minute Liverpool 15th October 1872.

Character assigned *A 1 S.S. No 2-72



© 2019

Lloyd's Register Foundation

REPORT OF SURVEY TO THE BOARD OF TRADE

1854

"Baroda"
-23.453



© 2019
Lloyd's Register
Foundation