

# ANNUAL SURVEYS.

32652

No. 102 Survey held at London Date 11<sup>th</sup> October 1872  
 on the Green Stm "Aksai" Master X  
 Tonnage 1472 Built at Newcastle When built 1870 - 4 mo.  
 By whom built Leslie Owners Pass. Stm. Harz's Trading Comp.  
 Port belonging to Odessa Destined Voyage Odessa  
 If Surveyed Afloat or in Dry Dock Victoria Dock. Pontoon.

Last Survey, No. 9813 Port of Iron. Classed B/I  
2-72

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Lead</u> When put on <u>1870</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined  
Bottom cleaned and coated with patent composition  
Is now in good and efficient condition, and  
in my opinion eligible to remain as classed.  
 Committee's Minute 29<sup>th</sup> October 1872  
 Character assigned B 1 J. D. W. H. H. Turner  
 Certificate (if required).

No. 153 Survey held at London Date 23<sup>rd</sup> Oct. 1872  
 on the Green Stm "Scotland" Master James  
 Tonnage 2057 Built at Kinghorn When built 1869 - 9 mo  
 By whom built Key. Owners Semperley & Co  
 Port belonging to London Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Thames limited Dry dock

Last Survey, No. 10080 Port of Iron. Classed B/I  
4-72

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Lead</u> When put on <u>1870</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined  
Bottom cleaned, and coated with M. L. Smith's composition  
Is now in good and efficient condition and in my  
opinion eligible to remain  
 Committee's Minute 29<sup>th</sup> October 1872  
 Character assigned B 1 J. D. W. H. H. Turner  
 Certificate (if required).