

# ANNUAL SURVEYS.

No. 2470 Survey held at Birkenhead Date Sept. 9<sup>th</sup> 1872  
on the (Iron) S.S. "Good Hope" Master Baunton  
Tonnage 1561 Built at Sunderland When built 1868-6 mo  
By whom built Laury Owners C. G. & J. H. Co.  
Port belonging to London Destined Voyage U. States  
If Surveyed Afloat or in Dry Dock In Messrs. Clossers graving dock

Last Survey, No. 10568 Port of Iron.

Classed 90 A1  
S.S. Sta. No. 1-71 72

The present Condition of the

Decks	<u>Good where seen</u>	Transoms <u>Reverts</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson	Pumps	
Comings		Transoms, Pointers, and Crutches	Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	Masts, Yards, &c.	<u>L</u>
Lower Deck Beams & Fastenings		Ditto ditto at other places	Sails	
Plank-sheers		Keelsons	Anchors, No. of	<u>efficient</u>
Sheerstrakes		Clamps and Shelves	Cables	<u>where</u>
Upsides		Ceiling	Hawsers and Warps	<u>seen</u>
Valves		Rudder	Standing and Running Rigging	
Plank (Bottom) and Counter		Copper <u>Cem</u> When put on <u>68</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The bottom scraped & painted. This vessel is now in good condition & in my opinion eligible to remain as Classed.

Committee's Minute Liverpool 1<sup>st</sup> November 1872

Character assigned 90 A1

E. C. Wheeler

Certificate (if required).

No. 819 Survey held at Liverpool Date Oct. 16<sup>th</sup> 23<sup>rd</sup> 1872  
on the (Iron) "Aurora de Nuestra Señora" Master H. Macho  
Tonnage 193 Built at S. Shields When built 1864-6 mo  
By whom built Readhead Owners H. Lavin  
Port belonging to Porto Rico Destined Voyage W. Indies  
If Surveyed Afloat or in Dry Dock Afloat & in (Panning) graving dock

Last Survey, No. 9517 Port of Iron.

Classed \* A-1  
S.S. Sta. No. 1-70 11-71

The present Condition of the

Decks	<u>Good where seen</u>	Transoms <u>Reverts</u>	Windlass and Capstan	<u>Good</u>
Waterways		Breasthooks and Stemson	Pumps	
Comings		Transoms, Pointers, and Crutches	Boats <u>one new</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	Masts, Yards, &c.	<u>L</u>
Lower Deck Beams & Fastenings		Ditto ditto at other places	Sails	
Plank-sheers		Keelsons	Anchors, No. of	<u>efficient</u>
Sheerstrakes		Clamps and Shelves	Cables	<u>where</u>
Upsides		Ceiling	Hawsers and Warps	
Valves		Rudder	Standing and Running Rigging	<u>seen</u>
Plank (Bottom) and Counter		Copper <u>Cem</u> When put on <u>70</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

The bulwark repaired & bottom scraped & painted. This vessel is now in good condition & in my opinion eligible to remain as Classed.

Committee's Minute Liverpool 1<sup>st</sup> November 1872

Character assigned A1

E. C. Wheeler

Certificate (if required).




THOMAS STUBBS

"Good Hope"

8

"Maurice de Vostre"  
Denver

23490



© 2019

Lloyd's Register  
Foundation