

ANNUAL SURVEYS.

32650

No. 487 Survey held at London Date 18th Octor 1872
 on the Ship City of Bombay Master H. Adair
 Tonnage 991 Built at Glasgow When built 1862 - 3 mo
 By whom built Stephen Owners Smith & Sons
 Port belonging to Glasgow Destined Voyage India
 If Surveyed Afloat or in Dry Dock Portoon Victoria Dock

Last Survey, No. 9717 Port of Iron Classified Fall

The present Condition of the

Decks	Treenails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Bottom cleaned and coated with M. J. Union Composition
Is now in good and efficient condition and in
my opinion eligible to remain as classed

Committee's Minute 29th October 1872

Character assigned A 1

IRW

Certificate (if required).

IRON 452-0331