

ANNUAL SURVEYS.

10723

Recd 11/11/72

[Signature]

No. 6260 Survey held at Gretnock Date 21st to 25th Octo 18 72
465 on the Iron Barque "Cingalese" Master Scott
 Tonnage 698 Built at Glasgow When built 1869 11th Month
 By whom built London & Glasgow Co. Owners Kenneth & Co.
 Port belonging to Glasgow Destined Voyage Clyde to Rio de Janeiro
 If Surveyed Afloat or in Dry Dock In dry dock

Last Survey, No. 4648 Port of Iron Classed * A 1 11/71

The present Condition of the

Decks	<u>Good where seen</u>	Timber <u>Rivets</u>	<u>Good where seen</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>do do</u>	Breasthooks and Stems	<u>do do</u>	Pumps	<u>do</u>
Comings	<u>do do</u>	Transoms , Pointers, and Crutches	<u>do do</u>	Boats	<u>do</u>
Upper Deck Beams & Fastenings	<u>do firm</u>	Timbers of the Frames at the Openings	<u>do do</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do firm</u>	Do Do at other places	<u>do do</u>	Sails	<u>Well found</u>
Planksheers	<u>Good where seen</u>	Keelsons	<u>do do</u>	Anchors	No. of <u>3 Bowers & Stream</u> & <u>2 Kedges</u>
Sheerstrakes	<u>Plating do do</u>	Clamps and Shelves	<u>do do</u>	Cables	<u>Complete</u>
Topsides	<u>do do do</u>	Ceiling	<u>do do</u>	Hawsers and Warps	<u>Sufficient</u>
Wales	<u>do do do</u>	Rudder	<u>do do</u>	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	<u>do do do</u>	Copper <u>Bottom Coated</u> When put on <u>now do do</u>			

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where examined

Now done. Vessel placed in dry dock, bottom scraped and coated with Red lead and Patent Grease. I am of opinion this vessel is eligible to remain as classed.

Committee's Minute 12th Nov 18 72
 Character assigned * A 1

[Signature]

© 2019 Lloyd's Register Foundation
H/18 0004
 Special fee £1.10
 Certificate (if required) Yes

120N452-0342