

ANNUAL SURVEYS.

3168

2

No. 40 Survey held at London Date Nov^r 6th 1872
 on the Iron Screw Ste. Eastella Master Neubaur
 Tonnage 974^{1/2} Built at Sunderland When built 1871
 By whom built Blumer Owners Jackson & Co.
 Port belonging to Hull Destined Voyage
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 9510 Port of Iron. Classed 90. A.A.
 11-71

The present Condition of the

Decks	good	Treenails	Rivets good where seen	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors, No. of	3 B. 1 S. 2 K
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder	efficient	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good.

Cleaned the bottom and recoated it.

She is in good condition and eligible to

remain as class'd 90. A. 1.

Samuel Presious

Committee's Minute 19th Nov 1872

Character assigned

90

T.P.M.

Certificate (if required)

No. 63 Survey held at London Date Nov^r 6th 1872
 on the Iron Screw Ste. Gazelle Master Pyman
 Tonnage 563 Built at Harlepool When built 1869
 By whom built Whitby Owners Cory & Co.
 Port belonging to W. Harlepool Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 9233 Port of Iron. Classed A.A.
 7-71

The present Condition of the

Decks	good	Treenails	Rivets where seen good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors, No. of	3 B. 1 S. 2 K
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder	efficient	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper	When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good

Cleaned the bottom and recoated it. Lifted a strake of ceiling fore and aft each side, at the bilges, found the cement good. Renewed a length of deck on the starboard side, and made good the caulking of deck. She is in good condition and entitled to remain as class'd A.A. 1.

Committee's Minute 19th Nov 1872

Character assigned

A

T.P.M.

Certificate (if required)

Eastlella



© 2019

Lloyd's Register
Foundation