

ANNUAL SURVEYS.

No.

Survey held at London

Dated to 13 Nov. 1872

on the

"Himalaya"

Master

A. W. Friston

Tonnage

1008

Built at

Sunderland

When built

1863

By whom built

Pile

Owners

G. O. Yessers

Port belonging to

London

Destined Voyage

New Zealand

If Surveyed Afloat or in Dry Dock

Canal Dry Dock and E. I. Dock.

Last Survey, No.

8438

Port of

Iron.

Classed

* A 1

S.S. No 3 - '69

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plating

Plank (Bottom) and Counter

Greenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

General Observations and Opinion,

Keel placed on blocks. Bottom scraped and coated with Paint and Gallor. Flat of Deck examined. Pieces inserted to make fair hulls & caulked where necessary. She appears in good condition and eligible to remain as

Committee's Minute 15 November 1873

Character assigned

* A 1

Henry J. Furness
Certificate (if required).

IRON 52-0399