

ANNUAL SURVEYS.

No. 641 Survey held at London Date 5th 20th Nov^r 18⁷²
 on the Sh. S. "Frisette" Master Phillips
 Tonnage 1197 Built at Ramsley When built 1863
 By whom built Gibson Owners Shaw-Savill & Co
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat ✓ in Dry Dock Green's Lower Dock Blackwall

Last Survey, No. 9568 Port of Iron

Classed * A 1 11.71
"S. S. No 2 - 71"

The present Condition of the

Decks	Greenails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the Openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>where</u>	Ditto ditto at other places <u>where</u>	Sails <u>and</u>
Planksheers <u>seen</u>	Keelsons <u>seen</u>	Anchors, No. of <u>Suff.</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plating	Copper <u>Paint</u> When put on <u>Now</u>	
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Placed on blocks in graving dock. Bottom cleaned & coated with Red and White Lead Paint, and one coat of M^r Gray's Patent Composition. Upper deck covered through out - vessel appears in efficient condition and eligible to remain as classed.

Committee's Minute 26th Nov^r 18⁷²

Character assigned * A 1

Henry. J. Tyrrell
 Certificate (if required).

No. 336 Survey held at London Date 5th 20th Nov^r 18⁷²
 on the Sh. S. "Dorham" Master H. Sexton
 Tonnage 998 Built at Sunderland When built 1866
 By whom built Ward Owners Temperley & Co
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat ✓ in Dry Dock Green's Lower Dock and E. S. Dock

Last Survey, No. 9620 Port of Iron

Classed * A 1 12.71
S. S. No 1. '70

The present Condition of the

Decks	Greenails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame at the Openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>where</u>	Ditto ditto at other places <u>where</u>	Sails <u>and</u>
Planksheers <u>seen</u>	Keelsons <u>seen</u>	Anchors, No. of <u>Suff.</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plating	Copper <u>Paint</u> When put on <u>Now</u>	
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Placed on blocks in graving dock. Bottom cleaned and coated with Patent Paint - She appears in good condition and eligible to remain as classed.

Committee's Minute 26th Nov^r 18⁷²

Character assigned * A 1

Henry. J. Tyrrell
 Certificate (if required).