

# ANNUAL SURVEYS.

No. 11955 Survey held at Newcastle Date 4<sup>th</sup> November 1872.  
 on the Iron S.S. "Kelloe" Master James Gunn  
 Tonnage 500 Built at Sunderland When built 1866 - 8 mo  
 By whom built Laing Owners J. D. Hill  
 Port belonging to London Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Cleland's Slipway

Last Survey, No. 9457 Port of Iron.

Classed A1  
S.S. No 2 - 71.

The present Condition of the

Decks	Treenails <u>Rivets.</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	<u>Framing</u>	Sails
Planksheers	Ditto ditto at other places	Anchors No. of
Sheerstrakes	Keelsons	Cables
Topsides	Clamps and Shelves	Hawsers and Warps
Wales	Ceiling	Standing & Running Rigging
Plank (Bottom) and Counter	Rudder	
	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where seen.

*This vessel's bottom has now been scraped and coated. She appears to be in good condition, and fit in my opinion to remain as classed A1.*

Committee's Minute 26<sup>th</sup> November 1872

L. H. Cooke.

Character assigned A1

*ITW*

Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register  
 Foundation

Certificate (if required).