

# ANNUAL SURVEYS.

No. 139 Survey held at London Date to 14 Dec<sup>r</sup> 18 42  
 on the Iron S.S. "Orchis" Master Ducas  
 Tonnage 1465 Built at Glasgow When built 1840  
 By whom built Laurie Owners Marpone & Co.  
 Port belonging to Liverpool Destined Voyage India  
 If Surveyed Afloat or in Dry Dock Wipams Dry Dock

Last Survey, No. 9909 Port of Iron. Classed 100 A.S.  
4/42

The present Condition of the

Decks	<u>Greenails</u> <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plating.	Copper <u>Paint</u> When put on <u>Now</u>	
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Placed on blocks. Bottom cleaned and coated with  
 Davidson's Patent Paint and Tallow. She appears in  
 good condition & eligible to remain as classed A.S.  
 Committee's Minute 20 Dec<sup>r</sup> 18 42 Henry. J. Tyrrell  
 Character assigned 100

Certificate (if required).

No. 24 Survey held at London Date to 19 Dec<sup>r</sup> 18 42  
 on the Iron S.S. "T. Apsland" Master Rayne  
 Tonnage 1269822 Built at Glasgow When built 1842  
 By whom built Barclay Owners Hull, Leith & Hambury S.P. Co  
 Port belonging to Leith Destined Voyage Cape of Good Hope  
 If Surveyed Afloat or in Dry Dock Wipams Dry Dock & S. H. S. Dock

Last Survey, No. 10720 Port of Iron. Classed 100 A.S.  
11, 12

The present Condition of the

Decks	<u>Greenails</u> <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plating	Copper <u>Paint</u> When put on <u>Now</u>	
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Placed on blocks. Bottom cleaned and coated with  
 McInnes's Patent Paint. She appears in good condition  
 and eligible to remain as classed A.S.  
 Committee's Minute 20 Dec<sup>r</sup> 18 42  
 Character assigned 100

Certificate (if required).