

10963  
**ANNUAL SURVEYS.**

~~32777~~

No. *Supp* Survey held at *London* Date *5<sup>th</sup> Jan<sup>y</sup>* 18*73*.  
 on the *Iron S.S. Walmer Castle* Master *Adams*  
 Tonnage *2439* Built at *Glasgow* When built *1872* 4 Mo.  
 By whom built *Barclay* Owners *Donald barrie & Co.*  
 Port belonging to *London* Destined Voyage *China*  
 If Surveyed Afloat or in Dry Dock *Repairs Dry Dock*

Last Survey, No. *10445* Port of *Iron* Classed *100 A 1* 8.72.

The present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>Good and Suffs.</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Opening		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors, No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing and Running Rigging	
Plank (Bottom) and Counter		Copper		When put on <i>Iron</i>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways  
*Placed on blocks - Bottom now cleaned and painted. Vessel appears in good condition and eligible to remain as classed "A 1".*  
*Henry L. G. G. G.*

Committee's Minute *10<sup>th</sup> Jan<sup>y</sup>* 18*73*  
 Character assigned *100 A 1*

*ITW*

Certificate (if required).

No. *34* Survey held at *London* Date *5<sup>th</sup> Jan<sup>y</sup>* 18*73*.  
 on the *Iron S.S. "Hong Kong"* Master *Symington*  
 Tonnage *1881* Built at *Newcastle* When built *1871* 2 mo.  
 By whom built *1221* Owners *E. A. Wall*  
 Port belonging to *London* Destined Voyage *China*  
 If Surveyed Afloat or in Dry Dock *Green's Dry Dock*

Last Survey, No. *10412* Port of *Iron* Classed *100 A 1* 1.72

The present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>Good and Suffs.</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Opening		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors, No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing and Running Rigging	
Plank (Bottom) and Counter		Copper		When put on <i>Iron</i>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways  
*Placed on blocks - Bottom scraped and painted, and new screwpropeller fitted - Vessel appears in good condition and eligible to remain as classed "A 1".*  
*Henry L. G. G. G.*

Committee's Minute *10<sup>th</sup> Jan<sup>y</sup>* 18*73*  
 Character assigned *100 A 1*

*ITW*

Certificate (if required).