

No. *338*

Survey held at

*London 10972*

Date

*14 Jan<sup>y</sup> 1873*

on the

*Iron Ship "Rostin Castle" Master*

Tonnage

*1170 Built at Glasgow*

When built

*1863 - 7 mo*

By whom built

*Napier*

Owners

*Currie & Co*

Port belonging to

*Liverpool*

Destined Voyage

*Calcutta*

If Surveyed Afloat or in Dry Dock

*Canal Dry Dock and S.W. I. Dock*

Last Survey, No.

*9776*

Port of

*Iron*

Classed

*\* A 1**S.S. No. 2 - 71 12.71*

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

*Plating*

Plank (Bottom) and Counter

Freenails

*Paint*

Breasthooks and Stemson

Transoms, Pointers, and Crutches

~~Timbers~~ of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

*Paint* When put on *Now*

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Placed on blocks - bottom cleaned and coated with *Pat. Paint*. Vessel appears in very good condition and eligible to receive as *Classed* *\* A 1*.

Committee's Minute *London, 17<sup>th</sup> January 1873.*

Character assigned

*\* A 1**Henry J. Gervel*

Certificate (if required).