

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 23572** Survey held at Liverpool Date, first Survey 10th Dec Last Survey 24 Dec 1872
 on the Iron S. "Strakblane" Master J. Poe

Tonnage 1364 built at Glasgow When built 1868-10 mo

By whom built Barclay Owners J & A Allan

Port belonging to Glasgow Destined Voyage India

If Surveyed Afloat or in Dry Dock Clarence dry dock & Afloat

Last Survey, No. 9797 Port Iron Classed *A 1
72

REPAIRS, &c.

Feeling equal to 2 courses lifted on each side all fore and aft and the cement coating. Floors &c examined and found good - bottom repainted

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Good

where

seen

seen

Good

Good

Fastenings

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shetfs

Ceiling

Rudder

Copper Cement When put on

Caulking of

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

The Amount of Entry Fee.....£ " : " : " is received by me,

Special.....3 : 3 : -

Certificate (if required) " : 5 : -

Committee's Minute Liverpool 10th January 1873

Character assigned *A 1 - Sept 11 72

Will: M. C. Davey



© 2019

Lloyd's Register Foundation

"Strathblane"
23572



© 2019

Lloyd's Register
Foundation