

106 No.

Survey held at

London 10996

Date

23 Jan<sup>r</sup> 1873

on the

Iron Steamer "Teriot"

Master

A. Nestle

Tonnage

1946  
1262

Built at

Gunderland

When built

1871-6 mo

By whom built

Hain

Owners

Norman &amp; Co

Port belonging to

London

Destined Voyage

India

If Surveyed Afloat or in Dry Dock

on the Victoria Dock Pontoon

Last Survey, No.

9443

Port of

Iron

Classed

No. 1

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams &amp; Fastenings

Lower Deck Beams &amp; Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

fence

When put on

1871

Caulking of Bottom, Deck, and Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &amp;c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

Caulking of Bottom, Deck, and Waterways

Bottom cleaned and coated with Paint and Tallow.

Is now in good, and efficient

Committee's Minute

28<sup>th</sup> January 1873

Character assigned

100A

condition and in my opinion

eligible to remain as classed

J. D. W.

A. H. Turner

Certificate (if required).