

ANNUAL SURVEYS.

No. 10438 Survey held at Liverpool Date 6th Feby 1873
 on the Iron S.S. "Dahlia" Master Crawford
 Tonnage 2011 Built at Liverpool When built 1872 - 5 mo
 By whom built 1304 Owners Narbone
 Port belonging to Liverpool Destined Voyage India
☒ Surveyed Afloat ☐ in Dry Dock Green's Upper Dock & S.W. Dock

Last Survey, No. 10438 Port of Liverpool Classed 100 A. 1

The present Condition of the

Decks	<u>Good</u>	<u>Rivets</u>	Windlass and Capstan
Waterways	<u>where</u>	Breasthooks and Stemson	Pumps
Comings	<u>seen</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto ditto at other places	Sails
Planksheers	<u>Good</u>	Keelsons	Anchors, No. of
Sheerstrakes	<u>Good</u>	Clamps and Shelves	Cables
Topsides	<u>Good</u>	Ceiling	Hawsers and Warps
Wales	<u>Good</u>	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	<u>Good</u>	Copper <u>Paint</u> When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Placed on blocks - Bottom cleaned and coated with Patent Paint - the appears in good condition and eligible to remain as classed A. 1.

Committee's Minute 14th Feby 1873

Character assigned

100A

IBM

Henry J. Syrett

Certificate (if required).

No. 10519 Survey held at Liverpool Date 6th Feby 1873
 on the Iron S.S. "Drummond Castle" Master Pitchie
 Tonnage 1985 Built at Glasgow When built 1871 - 12 mo
 By whom built 1350 Owners J. Minner
 Port belonging to Glasgow Destined Voyage India
☒ Surveyed Afloat ☐ in Dry Dock Green's Upper Dock & S.W. Dock

Last Survey, No. 10519 Port of Liverpool Classed 100 A. 1

The present Condition of the

Decks	<u>Good</u>	<u>Rivets</u>	Windlass and Capstan
Waterways	<u>where</u>	Breasthooks and Stemson	Pumps
Comings	<u>seen</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the Opening	Masts, Yards, &c.
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto ditto at other places	Sails
Planksheers	<u>Good</u>	Keelsons	Anchors, No. of
Sheerstrakes	<u>Good</u>	Clamps and Shelves	Cables
Topsides	<u>Good</u>	Ceiling	Hawsers and Warps
Wales	<u>Good</u>	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	<u>Good</u>	Copper <u>Paint</u> When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Placed on blocks - Bottom cleaned and coated with McAlister's Patent - screw propeller repaired - vessel appears in good condition and eligible to remain as classed

Committee's Minute 14th Feby 1873

Character assigned

100A

IBM

Henry J. Syrett

Certificate (if required).