

REPORT of SURVEY for REPAIRS.

11.110

Dec 20/2/73

No. in Reg. Book. **No.** 3142 Survey held at Hartlepool Date, first Survey 7th Jan Last Survey 9th Jan 1873
 on the S.S. "Kelloe" Master J. Gunn
 Tonnage 500 built at Sunderland When built 1866-8mo
 By whom built Laing Owners J. D. Hill
 Port belonging to London Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock In the Harbour

Last Survey, No. 10799 Port Shew Classed A1

REPAIRS, &c. now done through Damage. Two bent shell plates, at the light-water mark S. Side after body, the rivets taken out, heated set fair & a broad strap plate fitted inside & riveted through,

Present Condition of the

Decks	Trunnels <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights <u>Good</u>	Caulking of	
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Bottom, Deck, & Waterways <u>Good</u>	
General Observations and Opinion,	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
		Hatches <u>Good</u>

Is now in a good & efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the World & may in my opinion remain as now Classed A1

The Amount of Entry Fee.....£ : : is received by me, M. Gladstone

Special..... / : / : 0

Certificate (if required) : :

Committee's Minute 21st Febry 1873

Character assigned A1

J. D. Hill



© 2019

Lloyd's Register Foundation