

ANNUAL SURVEYS.

11122
 No. 2848 Survey held at Whitehaven Date 12th to 23rd February 1873
 on the Brigantine Jasper Master D. Nicholas
 Tonnage 188 Built at Whitehaven When built 1871 10th Mo
 By whom built Whitehaven Shipbuilding Company Owners G. Nelson & others
 Port belonging to Whitehaven Destined Voyage Trieste
 If Surveyed Afloat or in Dry Dock Patent Ship and afloat

Last Survey, No. 2770 Port of Whitehaven Iron Classed 100 A 1
11, 71

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Cemented</u> When put on <u>1871</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where seen

The bottom outside recoated with paint, and partially coated over the paint with tallow. This vessel is now in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 28th February 1873

Character assigned

100 A 1 IRW J. W. Miles
 Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register
 Foundation
 Certificate (if required).