

ANNUAL SURVEYS.

32950

No. 83 Survey held at London Date to 10 March 1873
 on the Iron Ship "Patriarch" Master Pile
 Tonnage 1339 Built at Herdeu When built 1869-9 mo
 By whom built Kood Owners Thompson
 Port belonging to Herdeu Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 1015 Port of Iron Classed A 1
 5.32

The present Condition of the

Decks	<u>Good</u>	Freemasts	<u>Pivots</u>	<u>Good</u>	Windlass and Capstan
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails
Planksheers	"	Keelsons	"	"	Anchors, No. of
Sheerstrakes	"	Clamps and Shelves	"	"	Cables
Topsides	"	Ceiling	"	"	Hawsers and Warps
Wales	"	Rudder	"	"	Standing and Running Rigging
Plating (Bottom) and Counter	<u>Plating</u>	Copper	<u>Paint</u>	When put on <u>Iron</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Placed on blocks - Bottom cleaned and coated with Patent Paint. Ship in good condition and eligible to remain as classed A 1

Committee's Minute 28th March, 1873

Henry J. Pyrell

Character assigned A 1

ITW

Certificate (if required).

No. 419 Survey held at London Date to 20 March 1873
 on the Iron Ship British Envoy Master McGrath
 Tonnage 1265 Built at Liverpool When built 1866-4 mo
 By whom built Royden Owners British Ship Owners Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Green's Upper Dock & S.W. Dock

Last Survey, No. 1004 Port of Iron Classed A 1
 5.3 4.57

The present Condition of the

Decks	<u>Good</u>	Freemasts	<u>Pivots</u>	<u>Good</u>	Windlass and Capstan
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails
Planksheers	"	Keelsons	"	"	Anchors, No. of
Sheerstrakes	"	Clamps and Shelves	"	"	Cables
Topsides	"	Ceiling	<u>Good</u>	"	Hawsers and Warps
Wales	"	Rudder	"	"	Standing and Running Rigging
Plating (Bottom) and Counter	"	Copper	<u>Paint</u>	When put on <u>Iron</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Placed on blocks - Rudder unlubed and some rivets in plating of ditto renewed. Bottom cleaned and coated with Pat Paint. Ship in good condition & eligible to remain as classed A 1

Committee's Minute 28th March, 1873

Henry J. Pyrell

Character assigned A 1

ITW

Certificate (if required).