

ANNUAL SURVEYS.

11195

32953

No. 650 Survey held at London Date 15 March 1873
 on the Ship "Star of Germany" Master Wilson
 Tonnage 1284 Built at Belfast When built 1872 - 3m
 By whom built Harland Owners Curry & Sons
 Port belonging to Belfast Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Canal Dry Dock

Recd. 26.3.73
 G. H. L.

Last Survey, No. 10155 Port of Iron Classed 100 A. 1
 5.72

The present Condition of the

Decks	<u>Good</u>	Freemasts	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails
Planksheers	"	Keelsons	"	"	Anchors, No. of
Sheerstrakes	"	Clamps and Shelves	"	"	Cables
Topsides	"	Ceiling	"	"	Hawsers and Warps
Wales	"	Rudder	"	"	Standing and Running Rigging
Plank (Bottom) and Counter	"	Copper	<u>Paint</u>	When put on <u>Nov.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Placed on blocks - Bottom cleaned and coated with
Pat Paint & McJannet's Compound - Vessel in excellent order
and eligible to remain as classed A. 1.

Committee's Minute 28th March, 1873

Character assigned 100 A

IFW

Certificate (if required).

No. 649 Survey held at London Date 21st March 1873
 on the Ship "Star of Erin" Master Hill
 Tonnage 949 Built at Belfast When built 1862
 By whom built Harland Owners Curry & Sons
 Port belonging to Belfast Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 10257 Port of Iron Classed * A 1
S.S. No 2:69 - 6.72

The present Condition of the

Decks	<u>Good</u>	Freemasts	<u>Rivets</u>	<u>Good</u>	Windlass and Capstan
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails
Planksheers	"	Keelsons	"	"	Anchors, No. of
Sheerstrakes	"	Clamps and Shelves	"	"	Cables
Topsides	"	Ceiling	"	"	Hawsers and Warps
Wales	"	Rudder	"	"	Standing and Running Rigging
Plank (Bottom) and Counter	"	Copper	<u>Paint</u>	When put on <u>Nov.</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Placed on blocks, outside surface of plating all scraped & scraped
& ironed to clean where accessible. Rudder unburnt & bushed
surface of plating cemented on quarters in way of water closets &c
and bottom coated with McJannet's Patent Paint. Vessel in good
condition & eligible to remain as classed

Committee's Minute 28th March, 1873

Character assigned * A 1

IFW

Certificate (if required).