

11195  
**ANNUAL SURVEYS.**

32953

No. 650 Survey held at London Date 15 March 1873.  
on the Steamship "Star of Germany" Master Wilson  
Tonnage 1284 Built at Belfast When built 1872 - 3m  
By whom built Harland Owners Curry & Sons  
Port belonging to Belfast Destined Voyage Bombay  
☒ Surveyed ~~Afloat~~ or in Dry Dock Canal Dry Dock

Recd. 26.3.73  
Guth

Last Survey, No. 10155 Port of Iron Classed 100 A. 1  
5.72

The present Condition of the

Decks	<u>Good</u>	Freemasts	<u>Pivots</u>	<u>Good</u>	Windlass and Capstan
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails
Planksheers	"	Keelsons	"	"	Anchors, No. of
Sheerstrakes	"	Clamps and Shelves	"	"	Cables
Topsides	"	Ceiling	"	"	Hawsers and Warps
Wales	"	Rudder	"	"	Standing and Running Rigging
Plank (Bottom) and Counter	"	Copper	<u>Paint</u>	When put on <u>Nov.</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good  
Placed on blocks - Bottom cleaned and coated with  
Pat Paint & McJannet's Compound - Vessel in excellent order  
and eligible to remain as classed A. 1.  
Committee's Minute 28th March, 1873 Henry J. Gynell.  
Character assigned 100 A. 1 J. P. W.  
Certificate (if required).

No. 649 Survey held at London Date 21 March 1873.  
on the Steamship "Star of Erin" Master Hill  
Tonnage 949 Built at Belfast When built 1862.  
By whom built Harland Owners Curry & Sons.  
Port belonging to Belfast Destined Voyage Bombay  
☒ Surveyed ~~Afloat~~ or in Dry Dock Canal Dry Dock

Last Survey, No. 10257 Port of Iron Classed \* A 1  
S. S. No. 2:69 - 6.72

The present Condition of the

Decks	<u>Good</u>	Freemasts	<u>Pivots</u>	<u>Good</u>	Windlass and Capstan
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails
Planksheers	"	Keelsons	"	"	Anchors, No. of
Sheerstrakes	"	Clamps and Shelves	"	"	Cables
Topsides	"	Ceiling	"	"	Hawsers and Warps
Wales	"	Rudder	"	"	Standing and Running Rigging
Plank (Bottom) and Counter	"	Copper	<u>Paint</u>	When put on <u>Nov.</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good  
Placed on blocks, outside surface of Plating all scraped, scraped  
& ironed to clean where accessible. Rudder unburnt & bushed  
inside of plating cemented on quarters in way of water closets &c.  
and bottom coated with McJannet's Patent Paint. Vessel in good  
condition & eligible to remain as classed  
Committee's Minute 28th March, 1873 Henry J. Gynell.  
Character assigned \* A 1 J. P. W.  
Certificate (if required).