

REPORT of SURVEY for REPAIRS.

No. in Nov³ 527 Survey held at Cardiff Date, first Survey March 18th Last Survey April 19th 1878
Reg. Book. 220 on the Iron Ship "Oxford" Master Thomas Beaver

Tonnage 1282 built at Switzerland When built 1869 9 mo

By whom built Oswato Owners Tomperley & Co

Port belonging to London Destined Voyage East Indies from Cardiff

If Surveyed Afloat or in Dry Dock *Nov²⁵ Hile Bars Dry Dock & afloat*

Last Survey, No. 2781 Port London Classed A1

REPAIRS, &c. In Day Book, Scraped clean from lead line 12 feet —
above having been recently scraped and Painted, Outside
examined, several rivets concerned in Rudder, Bottom coated
up to lead line with Patent Composition, Inside examined
found recently Scraped and Painted, Painting all very good
and inside free from corrosion, Batches all taken up
in the flat, House Cementing in excellent condition, all
adhering firmly to the Plating and other parts, Lead
Angle Irons well covered with Cement, Floor Plates &c
all very free from corrosion.

Damage repairs, Several of the Iron Hankies,
to Bulwarks, broken, and some bent all taken out and
properly repaired, and refastened. Boats' Sides, and Hankies
for the same, repaired, and fixed. Twenty feet Pinrail on
each side, Ring bolts for securing Boats' Decks, Iron Strap
for Japan at City repaired. Two over Life Boats, One Boat
Present Condition of the repaired, and Hatches repaired. L. O.

Present Condition of the <u>Ship</u> , and <u>Hatches</u> repaired.		Iron Patent	
Decks	Good	Treenails	Good
Waterways	do	Breasthooks and Stem	do
Comings	do	Transoms, Pointers, and Crutches	do
Upper Deck Beams & Fastenings	do	Timbers of the Frame at the openings	do
Lower Deck Beams & Fastenings	do	Ditto Ditto at other places	do
Planksheers	Plating	Keelsons	do
Sheerstrakes	all in	Clamps and Shelves	do
Topsides	good	Ceiling	do
Wales	condition	Rudder	do
Plank (Bottom) and Counter		Copper Nail When put on	Center
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Caulking of	
General Observations and Opinion.	Bottom, Deck, & Waterways	Standing & Running Rigging	do
	Scuppers	Cargo and Main Hatchways	good
	Hatches		good

This vessel being surveyed and found in good condition being free from corrosion, and maintaining so having finally to the Plating &c. I am of opinion she may remain as Cleared ~~At~~ ^{*} and S. Net survey 1893

The Amount of Entry Fee.....£ 2 : 0 : 0 is received by me,

Special...for... 2 : 2 : 0

Certificate (~~if~~ required) : 3 : a

Committee's Minute 25th April 1895

Character assigned

~~HA~~ S.S. No 1-73

Расселл Дэвид Рутвин

T. P. W.

1127 Jan

Supplied with a Stream Anchor 14. 0 0 including
Stocks, One 9 inch Hawser, and one 7 inch 90
fathoms each. All other equipments sufficient
and good.

Henry Baynes



© 2019

Lloyd's Register
Foundation