

11291  
**ANNUAL SURVEYS.**

Rec 24/4/92

No. 10557 Survey held at Sunderland Date 4th April 1877  
 on the Iron Ship Millwall Master \_\_\_\_\_  
 Tonnage 1175 Built at London When built 1863 - 10 mo  
 By whom built Millwall S.W.C. Owners Houghton Smith & Co  
 Port belonging to Liverpool Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock

*[Handwritten signature]*

Last Survey, No. 9775 Port of River of Mersey Classed \* 1/2  
 S. S. No 2-72  
 The present Condition of the  
 Bottom coated outside.

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>4</u>
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of <u>3</u>
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides <u>Plated</u>	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good  
*She is now in an efficient state of repair and in my opinion entitled to remain as classed*  
*Leahouse Martindale*  
 Committee's Minute 25th April 1873  
 Character assigned 7/1/1 *[Signature]*  
 Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors No. of _____
Sheerstrakes _____	Clamps and Shelves _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways \_\_\_\_\_  
 Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_



IRON453-0471