

ANNUAL SURVEYS.

32931

No. *115*

Survey held at *London*

Date *3rd March 4th*

18*73*

on the *Iron Ship Ben Nevis*

Master *Mr. Peirie*

Tonnage *1055* Built at *Glasgow*

When built *1868 - buco*

By whom built *Barclay*

Owners *Watson Bros*

Port belonging to *Glasgow*

Destined Voyage *Glasgow*

If Surveyed Afloat or in Dry Dock *Mill Wall dry dock*

Last Survey, No. _____

Port of _____

Classed *A. 1.*

The present Condition of the

Decks <i>good</i>	Freemasts <i>Rivets</i>	<i>good</i>	Windlass and Capstan <i>in good order</i>
Waterways <i>"</i>	Breasthooks and Stemson <i>"</i>	<i>"</i>	Pumps <i>"</i>
Comings <i>"</i>	Transoms, Pointers, and Crutches <i>"</i>	<i>"</i>	Boats <i>"</i>
Upper Deck Beams & Fastenings <i>"</i>	Timbers of the Frame at the Openings <i>"</i>	<i>"</i>	Masts, Yards, &c. <i>"</i>
Lower Deck Beams & Fastenings <i>"</i>	Ditto ditto at other places <i>"</i>	<i>"</i>	Sails <i>"</i>
Planksheers <i>"</i>	Keelsons <i>not seen</i>		Anchors, No. of <i>3 B. 1 S. 2 H</i>
Sheerstrakes <i>"</i>	Clamps and Shelves <i>"</i>	<i>"</i>	Cables <i>"</i>
Topsides <i>"</i>	Ceiling <i>"</i>	<i>"</i>	Hawsers and Warps <i>"</i>
Wales <i>"</i>	Rudder <i>efficient</i>	<i>good</i>	Standing and Running Rigging <i>"</i>
Blank (Bottom) and Counter <i>"</i>	Copper <i>When put on</i>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways *good*

Cleaned and recoated the bottom. Examined her outside also inside as far as practicable. Directed the attention of the Owners or their Agents to the Rules Survey No. 1, (per notice card), the hold being full of ballast and lumber

Committee's Minute

The 4th March 1873

It is to be cleared at Glasgow when the Survey will be completed.

Character assigned _____

Samuel Presons

Certificate (if required).

IRON 454-0009

Revd 11.5.73

Ben. W. W. W.
Lancaster



© 2019

Lloyd's Register
Foundation