

# ANNUAL SURVEYS.

No. 132 Survey held at London Date 4<sup>th</sup> May 1873.  
 on the Iron Ship "Hawarden Castle" Master Matthews  
 Tonnage 1101 Built at Liverpool When built 1869 - 7 mo  
 By whom built Liverpool Owners Richards & Co  
 Port belonging to Liverpool Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Canal Dry Dock & T. W. I. D. K.

Last Survey, No.	Port of	Classed	* <u>A 1</u>
The present Condition of the			
Decks	<u>Good</u>	Freencails	<u>Pivots</u>
Waterways	"	Breasthooks and Stemson	
Comings	"	Transoms, Pointers, and Crutches	<u>Good</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	<u>where</u>
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	<u>seen</u>
Planksheers	"	Keelsons	
Sheerstrakes	"	Clamps and Shelves	
Topsides	"	Ceiling	
Wales	"	Rudder	<u>Good</u>
Plating	"	Copper	<u>Paint</u>
Plank (Bottom) and Counter	"	When put on	<u>down</u>
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways <u>Good</u>	
<p>Placed on blocks. Bottom cleaned and painted. Vessel appears in good condition so far as seen - but being overlaid with parts of outward Carpenters work, no special survey could be completed. Consequently S.S. No. 1 deferred until expiration of present voyage.</p>			
Committee's Minute	<u>20<sup>th</sup> May</u>	18 <u>73</u>	<u>Henry J. Gurnell</u>
Character assigned	* <u>A 1</u>	<u>T. W. I. D. K.</u>	
Certificate (if required).			

No. 665	Survey held at <u>London</u>	Date <u>15<sup>th</sup> May</u>	18 <u>73</u> .
on the <u>Iron Ship "Star of Scotia"</u>	Master <u>Smyth</u>		
Tonnage <u>999</u>	Built at <u>Belfast</u>	When built <u>1864</u>	
By whom built <u>Harland &amp; Co</u>	Owners <u>Curry &amp; Co</u>		
Port belonging to <u>Belfast</u>	Destined Voyage <u>Calcutta</u>		
If Surveyed Afloat or in Dry Dock	<u>Warrands Dry Dock</u>		
Last Survey, No. <u>10573</u>	Port of <u>London</u>	Classed	* <u>A 1 S.S. No 2</u>
The present Condition of the			
Decks	<u>Good</u>	Freencails	<u>Pivots</u>
Waterways	"	Breasthooks and Stemson	
Comings	"	Transoms, Pointers, and Crutches	<u>Good</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	<u>where</u>
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	<u>seen</u>
Planksheers	"	Keelsons	
Sheerstrakes	"	Clamps and Shelves	
Topsides	"	Ceiling	<u>Good</u>
Wales	"	Rudder	"
Plating	"	Copper	<u>Paint</u>
Plank (Bottom) and Counter	"	When put on	<u>down</u>
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways <u>Good</u>	
<p>Placed on blocks. Bottom cleaned &amp; coated with McInnes' Patent Compound. Inner surface of plating on Quarters, in way of Water Closets and Side Scuttles - chipped &amp; repaired. Painted &amp; cemented. Vessel in very good condition &amp; eligible to remain as classed.</p>			
Committee's Minute	<u>20<sup>th</sup> May</u>	18 <u>73</u>	<u>Henry J. Gurnell</u>
Character assigned	* <u>A 1</u>	<u>T. W. I. D. K.</u>	
Certificate (if required).			