

30/1/73 ✓

11455

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. No. 23756 Survey held at Birkenhead Date, first Survey July 10 Last Survey July 27 1873
on the Ship "Francis Thorpe" Master H. Buck
Tonnage 1297 built at Stonington When built 1860-11 mo
By whom built Richardson Owners Thorpe & Co
Port belonging to Liverpool Destined Voyage India
If Surveyed Afloat or in Dry Dock Afloat & in Great Float-graving dock
Last Survey, No. 1939 Port Iron Classed * A-1
REPAIRS, &c. None done 70

Ceiling equal to one strake & the lumber boards both sides fore & aft lifted - found the plates, rivets & Cement in good condition, & the hull scraped & painted where required —

Present Condition of the

Decks	Trunnels <u>Rivets</u>	Windlass and Capstan <u>Good & efficient</u>
Waterways	Breasthooks and Stemson	Pumps <u>" "</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>" "</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>" "</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>Seen from deck</u>
Planksheers	Keelsons	Sails <u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>efficient</u>
Topsides	Ceiling	Cables <u>where</u>
Wales	Rudder	Hawsers and Warps <u>seen</u>
Plates (Bottom) and Counter	Copper <u>Cem</u> When put on <u>60</u>	Standing & Running Riggings <u>Good</u>
Engine Room Skylights	Caulking of	Cargo and Main Hatchways <u>Good</u>
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>Satisfactory</u>	Hatches <u>Good</u>
Scuppers		

General Observations and Opinion,

This Vessel is now in good condition & in my opinion eligible to remain as Classed, & marked S. S. No. 1-73.

The Amount of Entry Fee.....£ — : — : — is received by me,

Special..... 3 : 3 : " 31/5/73
Certificate (if required) — : — : —

Committee's Minute Liverpool 3rd Decr 1873

Character assigned * A-1 - S. S. No. 1-73

W. C. Wheeler



© 2019
Lloyd's Register
Foundation

"Francis Thorpe"
23456



© 2019

Lloyd's Register
Foundation