

213


No. 64 Annual Survey held at Genoa  
on the "Stato Platense" Sew.

11540

Date 11/1/73 26 June 1873

Master N. Santandari

Tonnage 1698 Built at London

When built 1870. 1<sup>mo</sup>.By whom built DudgeonOwners A. OnetoPort belonging to GenoaDestined Voyage River PlateIf Surveyed Afloat or in Dry Dock In dry dock

*[Handwritten signature]*

Last Survey, No. 1999 Port of GenClassed \*A.1  
5.70

The present Condition of the

Decks good - now paintedWaterways goodComings d<sup>o</sup>Upper Deck Beams & Fastenings good - now paintedLower Deck Beams & Fastenings d<sup>o</sup> d<sup>o</sup>Planksheers goodSheerstrakes d<sup>o</sup>Topsides d<sup>o</sup>Wales d<sup>o</sup>~~Plank~~ (Bottom) and Counter good - bottom now painted.

General Observations and Opinion,

Treenails rivets goodBreasthooks and Stems d<sup>o</sup>Transoms, Pointers, and Crutches d<sup>o</sup>~~Timbers~~ of the Frame at the Openings d<sup>o</sup>~~Ditto~~ ditto at other places d<sup>o</sup>Keelsons d<sup>o</sup>Clamps and Shelves d<sup>o</sup>Ceiling d<sup>o</sup>Rudder d<sup>o</sup>~~Copper~~ Cement When put on 1870Caulking of Bottom, Deck, and Waterways good.Windlass and Capstan goodPumps d<sup>o</sup>Boats d<sup>o</sup>Masts, Yards, &c. d<sup>o</sup>Sails d<sup>o</sup>Anchors, No. of 3 B. 1 S. 2 K.Cables goodHawsers and Warps d<sup>o</sup>Standing and Running Rigging d<sup>o</sup>

The cement and rivets were tested in several places and found good.  
The vessel is in a good and efficient condition and fit in my opinion  
to remain as classed \*A.1.

Committee's Minute 4<sup>th</sup> July, 1873Character assigned \*A.1

*[Handwritten signature]*

*[Handwritten signature]*

Certificate (if required).