

# ANNUAL SURVEYS.

No. 10461 Survey held at London Date 16<sup>th</sup> June 1873  
 on the Iron Screw Steamer H. P. Stephenson Master Tak Floole  
 Tonnage 962 Built at Newcastle When built 1871 - 11 mo  
 By whom built Richardson Owners Gen<sup>l</sup> Iron Screw Col<sup>l</sup> Com<sup>y</sup>  
 Port belonging to London Destined Voyage Mediterranean  
 If Surveyed Afloat or in Dry Dock Com<sup>l</sup> dry dock

Last Survey, No. 10461 Port of Brown Classed 90. A. 1.

The present Condition of the

Decks <u>good</u>	Freemasts <u>Rivess</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors, No. of <u>3 B. 1 S. 2 K</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>efficient</u>	Standing and Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>When put on</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Cleaned and recoated the bottom. - She is now in good condition, and  
I am of opinion she is entitled to remain as

Committee's Minute 27<sup>th</sup> June, 1873

Character assigned 90 A. 1.

Class'd 90 A. 1.  
Samuel Presious

Certificate (if required).

No. 9065 Survey held at London Date 17<sup>th</sup> June 1873  
 on the Iron Screw Steamer Galicia Master W. J. Earle  
 Tonnage 750 Built at Hartlepool When built 1866 - 4 mo  
 By whom built Richardson Owners J. Hall jun<sup>r</sup> & Co.  
 Port belonging to London Destined Voyage Lisbon  
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 9065 Port of Brown Classed A. 1.

The present Condition of the

Decks <u>good</u>	Freemasts <u>Rivess</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors, No. of <u>3 B. 1 S. 2 K</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>efficient</u>	Standing and Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>When put on</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Cleaned and recoated the bottom. She is now in good condition and I am  
of opinion she is entitled to remain as

Committee's Minute 27<sup>th</sup> June, 1873

Character assigned A. 1.

Class'd A. 1.  
Samuel Presious

Certificate (if required).