

S.S. No 3. 11577 ~~33/28~~ 30236

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey May 26 Last Survey June 23 18 73  
 on the S. "White Eagle" (Iron) Master Andrews  
 153 Tonnage 878 built at Glasgow When built 1855  
 By whom built \_\_\_\_\_ Owners Bilbe  
 Port belonging to London Destined Voyage Adelaide  
 If Surveyed Afloat or in Dry Dock West India Dock & Limehouse Dock  
 Last Survey, No. 10515 Port Iron Classed \* A 1

REPAIRS, &c.

The Hold closed and stagers made, all close ceiling removed; frames, stringers &c exposed; all oxidation removed, the plating bored and no perceptible diminution found in thickness, the cement all examined and a large portion renewed with Portland, the vessel recoated, the Windlass stripped and chains ranged —

Present Condition of the

Decks	} Good	Freeboards	} Good	Windlass and Capstan	} Good +
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 x 1 x 2</u>	
Topsides		Ceiling		Cables <u>300 fms</u>	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper		Standing & Running Rigging	
Engine Room Skylights	Caulking of				
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	Scuppers	Cargo and Main Hatchways	Hatches	

General Observations and Opinion, good

This vessel is now in a good and efficient state and having complied with all the requirements of the Rules Survey No 3 is eligible in my opinion to remain as classed \* A 1

The Amount of Entry Fee.....£ : : is received by me, and be marked  
 Special..... 6: 6: S.S. No 3. 73

Certificate (if required) : : :

Committee's Minute 7th July, 1873

Character assigned \* A 1

S.S. No 3-73

Thos. W. Wain



© 2019

Lloyd's Register Foundation