11657

ANNUAL SURVEYS.

Rec'd. 8.7.73

No. 629 Survey held at London Date 16th June & 5th July 1873

on the "Don L. Coldinghame" Master J. Whyte

Tonnage 1892 Built at Liverpool When built 1866 - 1 new

By whom built Hart Owners Willis & Son

Port belonging to London Destined Voyage Bombay

If Surveyed Afloat or in Dry Dock Canal Dry Dock & Victoria Dock

Last Survey, No. 9817 **Port of** Iron **Classed** * A 1 - 2.72
L.V.N° 1.72.

The present Condition of the

Decks	Good	Rivets ~~Treenails~~	Where seen good
Waterways	do	Breasthooks ~~and Sternson~~	do
Comings	do	Transoms, ~~Pointers~~, and Crutches	do
Upper Deck Beams & Fastenings	do	~~Timbers of the~~ Frame at the Openings	do
Lower Deck Beams & Fastenings	do	~~Ditto~~ ~~ditto~~ at other places	do
Planksheers		Keelsons	do
Sheerstrakes	do	Clamps and Shelfs	
Topsides	do	Ceiling	do
Wales		Rudder	do
~~Plank~~ Te (Bottom) and Counter	do	~~Copper~~ When put on	

Windlass and Capstan	
Pumps	
Boats	
Masts, Yards, &c.	
Sails	
Anchors, No. of	
Cables	
Hawsers and Warps	
Standing and Running Rigging	Good & Complement

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good

London. Bottom cleaned down and coated with three Coats of Mc Innis's patent paint. She is in a good and efficient condition, and is in my opinion eligible to remain

Committee's Minute 18th July, 1873 as classed

Character assigned * A 1 James M Neil

TBW Certificate (if required).

No. 643 Survey held at London Date 24th July 1873

on the "Don L. "Mid Surry" Master C. Harvey

Tonnage 835 Built at Newcastle When built 1870

By whom built Palmer Owners Dixon & Co

Port belonging to London Destined Voyage Lisbon

If Surveyed Afloat or in Dry Dock Regent Dry Dock

Last Survey, No. 9476 **Port of** Iron **Classed** 90 A 1
10.71

The present Condition of the

Decks	Good	Rivets ~~Treenails~~	Where seen good
Waterways	do	Breasthooks ~~and Sternson~~	do
Comings	do	Transoms, ~~Pointers~~, and Crutches	do
Upper Deck Beams & Fastenings	do	~~Timbers of the~~ Frame at the Openings	do
Lower Deck Beams & Fastenings	do	~~Ditto~~ ~~ditto~~ at other places	do
Planksheers	do	Keelsons	do
Sheerstrakes	do	Clamps and Shelfs	
Topsides	do	Ceiling	do
Wales		Rudder	do
~~Plank~~ Te (Bottom) and Counter	do	Copper When put on	

Windlass and Capstan	
Pumps	
Boats	
Masts, Yards, &c.	
Sails	
Anchors, No. of	
Cables	
Hawsers and Warps	
Standing and Running Rigging	Good & Complement

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good

London. Bottom cleaned, and coated with two coats of White Zinc paint, and one of Yellow. She in good condition,

Committee's Minute 18th July, 1873 and eligible to remain as classed

Character assigned 90 A 1 James M Neil

TBW Certificate (if required).

2000—13/2/71.

© 2019 Lloyd's Register Foundation

IRON454-0445