

ANNUAL SURVEYS.

33764

No. 819

Survey held at

London

Date

17. 20 June 1873.

on the

Green Stm "Miranda"

Master

E. Dilly

Tonnage

296

Built at

Newcastle

When built

1865 3 mo

By whom built

Palmer

Owners

London Stm Ship Comp. (Limo)

Port belonging to

London

Destined Voyage

Mediterranean

If Surveyed Afloat or in Dry Dock

On the Victoria Dock Pontoon.

Last Survey, No.

4369

Port of

Iron

Classed

80 A1

The present Condition of the

Decks

Good

Ironails

Rivets

Good

Windlass and Capstan

Good

Waterways

Breasthooks and Stemson

Pumps

Comings

Transoms, Pointers, and Crutches

Boats

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Masts, Yards, &c.

Lower Deck Beams & Fastenings

Ditto ditto at other places

Sails

Planksheers

Keelsons

Anchors, No. of

3 B. 15. 24

Sheerstrakes

Clamps and Shells

Cables

Good

Topsides

Ceiling

Hawsers and Warps

and

Wales

Rudder

Standing and Running Rigging

Sufficient

Plank (Bottom) and Counter

Copper

When put on

1865

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where examined.

Caulked. Butts, bottom cleaned and coated with Paint and Gallon. Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute

18th July. 1873

Character assigned

80 A1

IRW

W. H. Turner

Certificate (if required).

No. 163

Survey held at

London

Date

25 June 1873.

on the

Green Stm "Hector"

Master

T. Green

Tonnage

1979

Built at

Sunderland

When built

1863 4 mo

By whom built

Rainey

Owners

Gourley & Co

Port belonging to

Sunderland

Destined Voyage

Montreal

If Surveyed Afloat or in Dry Dock

Port Green's dry dock.

Last Survey, No.

10638

Port of

Iron

Classed

90 A1

The present Condition of the

Decks

Good

Ironails

Rivets

Good

Windlass and Capstan

Good

Waterways

Breasthooks and Stemson

Pumps

Comings

Transoms, Pointers, and Crutches

Boats

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Masts, Yards, &c.

Lower Deck Beams & Fastenings

Ditto ditto at other places

Sails

Planksheers

Keelsons

Anchors, No. of

3 B. 15. 24

Sheerstrakes

Clamps and Shells

Cables

Good

Topsides

Ceiling

Hawsers and Warps

and

Wales

Rudder

Standing and Running Rigging

Sufficient

Plank (Bottom) and Counter

Copper

When put on

port 1863

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where examined

Bottom cleaned and coated with patent composition Is now in good and efficient condition and in my opinion eligible to remain as classed.

Committee's Minute

18th July. 1873

Character assigned

90 A1

IRW

W. H. Turner

Certificate (if required).