

REPORT of SURVEY for REPAIRS.

No. in Reg. Book 23864 Survey held at Liverpool Date, first Survey July 9 Last Survey July 31 1873
 on the Iron 1" Iron Tube Master Edgar
 Tonnage 1435 built at Liverpool When built 1863-3 mo
 By whom built Lawrence Owners Hargrove & Co
 Port belonging to Liverpool Destined Voyage India
 If Surveyed Afloat or in Dry Dock Afloat & in London graving dock
 Last Survey, No. 9639 Port Liverpool Classed * A 1 - 10.71
 REPAIRS, &c. Now done to complete S.S. No. 2 - please see London report No. 9639.

Nearly all the Ceiling in flat of bottom & part at the bilges taken up, all oxidation removed - found the plates, rivets, & Cement in good condition, & the hull painted where required.

Present Condition of the

Decks	<u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u>	Transoms, <u>Pointers</u> , and Crutches	<u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u> <u>Good</u>	Windlass and Capstan <u>Good & efficient</u>
Waterways		Breasthooks and Stems		Pumps
Comings		Timbers of the Frame at the openings		Boats
Upper Deck Beams & Fastenings		Ditto Ditto at other places		Masts, Yards, &c.
Lower Deck Beams & Fastenings		Keelsons		Condition, how ascertained <u>seen from deck</u>
Planksheers		Clamps and Shells		Sails
Sheerstrakes		Ceiling		Anchors No. of
Topsides		Rudder		Cables
Wales		Copper <u>Cem</u> When put on <u>15</u>		Hawsers and Warps
Plates Plank (Bottom) and Counter		Caulking of		Standing & Running Rigging <u>Efficient</u>
Engine Room Skylights	Bottom, Deck, & Waterways <u>Good</u>	Cargo and Main Hatchways <u>Good</u>		
Coal Bunker, Openings, Lids, &c.	Scuppers <u>Good</u>	Hatches <u>Good</u>		

General Observations and Opinion,

This Vessel is now in good condition & in our opinion eligible to remain as Classed, & marked S.S. No. 2. 71

The Amount of Entry Fee.....£ - : - : - is received by me,

Special.....3 : 3 : " 19/8/73 R.M.

Certificate (if required) - : - : -

Committee's Minute Liverpool 22nd August 1873

Character assigned * A 1 - S.S. No. 2 - 71 -

W. B. Wheeler
Will B. Wheeler
 Lloyd's Register Foundation

REPORT OF SURVEY OF REPAIRS

Don Burke



© 2019

Lloyd's Register Foundation