

ANNUAL SURVEYS.

No. 167 Survey held at London Date 23 Augth Feb^{ry} 1873
 on the Iron Ship Bharwar Master J. A. Frebody
 Tonnage 1293 Built at Belfast When built 1864
 By whom built Harland Owners J. Willis
 Port belonging to London Destined Voyage Melbourn
 If Surveyed Afloat or in Dry Dock Union Dry Dock S.W. India Docks

Last Survey, No. 10578 Port of Iron Classed A.1
 The present Condition of the
 Decks good Freenails Rivets good Windlass and Capstan in good order
 Waterways // Breasthooks and Stemson // Pumps //
 Comings // Transoms, Pointers, and Crutches // Boats //
 Upper Deck Beams & Fastenings // Timbers of the Frame at the Openings // Masts, Yards, &c. //
 Lower Deck Beams & Fastenings // Ditto ditto at other places // Sails //
 Planksheers // Keelsons // Anchors, No. of 3 B. 1 S. 2 K
 Sheerstrakes // Clamps and Shelves // Cables //
 Topsides // Ceiling // Hawseers and Warps //
 Wales // Rudder efficient Standing and Running Rigging //
 Plank (Bottom) and Counter // Copper When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Cleaned the bottom and recoated it
She is in good condition, and in my opinion entitled to remain as
Classed A.1.

Committee's Minute 12th September 1873.

Character assigned A.1

Certificate (if required).

No. 336 Survey held at London Date 5th Feb^{ry} 10th 1873
 on the Iron Barque Hopeful Master H. M. Lely
 Tonnage 332 Built at Port Glasgow When built 1866
 By whom built Kirkpatrick Owners H. Stanes
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Union Dry dock

Last Survey, No. 9772 Port of Iron Classed A.1
 The present Condition of the
 Decks good Freenails Rivets good Windlass and Capstan in good order
 Waterways // Breasthooks and Stemson // Pumps //
 Comings // Transoms, Pointers, and Crutches // Boats //
 Upper Deck Beams & Fastenings // Timbers of the Frame at the Openings // Masts, Yards, &c. //
 Lower Deck Beams & Fastenings // Ditto ditto at other places // Sails //
 Planksheers // Keelsons // Anchors, No. of 3 B. 1 S. 2 K
 Sheerstrakes // Clamps and Shelves // Cables //
 Topsides // Ceiling // Hawseers and Warps //
 Wales // Rudder efficient Standing and Running Rigging //
 Plank (Bottom) and Counter // Copper When put on

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good

Cleaned the bottom, shifted the Ballast, Cleaned her out, Repaired the Ceiling,
Rebuilt upper part of Rudder, Repaired Cements, - Star^{board} Cashead New,
She is in good and efficient condition, and in my opinion is entitled to remain as
Classed A.1.

Committee's Minute 12th September 1873.

Character assigned A.1

Certificate (if required).

Shawar d.
Asif



© 2019

Lloyd's Register
Foundation