

# ANNUAL SURVEYS.

495 No. 11879 Survey held at London Date 17th Sept. 1873  
 on the S. City of Bombay Master R. Adair  
 Tonnage 991 Built at Glasgow When built 1862-3  
 By whom built Stephens Owners Smith & Sons  
 Port belonging to Glasgow Destined Voyage Opulide  
 If Surveyed Afloat or in Dry Dock Greenhouse Dry Dock

Recd 12973

Last Survey, No. 10711 Port of Brown Classed A 1  
9.9.71. 10.72

The present Condition of the

Decks <u>Good</u>	Treenails <u>Where seen good</u>	Windlass and Capstan
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>do</u>	Sails
Planksheers <u>do</u>	Keelsons <u>do do do</u>	Anchors, No. of
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Cables
Topsides <u>do</u>	Ceiling <u>do do do</u>	Hawsers and Warps
Wales <u>do</u>	Rudder <u>do</u>	Standing and Running Rigging
Plank (Bottom) and Counter <u>do</u>	Copper <u>do</u> When put on <u>do</u>	

General Observations and Opinion, Good Caulking of Bottom, Deck, and Waterways Good

None done. Bottom cleaned and coated with M. Paris patent paint &c. She is in good condition and in my opinion eligible to remain as classed

Committee's Minute 26th Sept 1873

Character assigned A 1 James McNeil Certificate (if required).

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion, \_\_\_\_\_ Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_

Character assigned \_\_\_\_\_



© 2019

Lloyd's Register Foundation  
 Certificate (if required).

1R0N455-0172