

ANNUAL SURVEYS.

33346

No. 348 Survey held at London Date 15th Feb^r 23rd 1873
 on the Iron Ship Marpesia Master Thos Storey
 Tonnage 1443 Built at Port Glasgow When built 1866
 By whom built Reed Owners Heap & Sons
 Port belonging to Liverpool Destined Voyage Melbourn
 If Surveyed Afloat or in Dry Dock Union dry dock &

Recd 23.9.73
 [Signature]

Last Survey, No. 1998 Port of Liverpool Classed A.1. S.S. No 1/70

The present Condition of the					
Decks	<u>good</u>	Freeboards	<u>Rivets</u>	<u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails
Planksheers	"	Keelsons	"	"	Anchors, No. of <u>3 B. 1 S. 2 K</u>
Sheerstrakes	"	Clamps and Shelves	"	"	Cables
Topsides	"	Ceiling	"	"	Hawsers and Warps
Wales	"	Rudder <u>efficient</u>	"	"	Standing and Running Rigging
Plank (Bottom) and Counter	"	Copper	When put on		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good.
She is in good and efficient condition and is in my opinion entitled to remain as classed
Recoated the bottom.
 Committee's Minute 30th Sept 1873
 Character assigned A.1. Samuel Presious
 Certificate (if required).

No. 84 Survey held at London Date 13th Feb^r 1873
 on the Iron Ship Salado Master James Johnson
 Tonnage 442 Built at Port Glasgow When built 1866
 By whom built Kaiserlich Owners Carmichael
 Port belonging to Greenock Destined Voyage Brisbane
 If Surveyed Afloat or in Dry Dock Canal dry dock & S.W. India docks

[Signature]

Last Survey, No. 9707 Port of Liverpool Classed A.1. S.S. No 1/69

The present Condition of the					
Decks	<u>good</u>	Freeboards	<u>Rivets</u>	<u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	Sails
Planksheers	"	Keelsons	"	"	Anchors, No. of <u>3 B. 1 S. 2 K</u>
Sheerstrakes	"	Clamps and Shelves	"	"	Cables
Topsides	"	Ceiling	"	"	Hawsers and Warps
Wales	"	Rudder <u>efficient</u>	"	"	Standing and Running Rigging
Plank (Bottom) and Counter	"	Copper	When put on		

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways good.
Cleaned and recoated or painted the bottom outside.
She is in good and efficient condition, and in my opinion is entitled to remain as classed
 Committee's Minute 30th Sept 1873
 Character assigned A.1. Samuel Presious
 Certificate (if required).

Lloyd's Register
 Foundation
 IRON 455-0184

Manuela
& Salado



© 2019

Lloyd's Register
Foundation