

# ANNUAL SURVEYS.

33382

No. 160 Survey held at London Date 26 Sept. 1873  
 on the General M<sup>r</sup> "Hinchin" Master J. J. Turroch  
 Tonnage 1558 Built at Glasgow When built 1872-7 mo  
 By whom built J. J. Turroch Owners Jenkins & Co  
 Port belonging to London Destined Voyage Bangor, N. Clyde.  
 If Surveyed Afloat or in Dry Dock James Limited Dry Dock

Last Survey, No. Port of Iron Classed 100A1

The present Condition of the

Decks	Good	Freecails	Ports	Good	Windlass and Cupstan
Waterways	✓	Breasthooks and Stenson		✓	Pumps
Comings	✓	Transoms, Pointers, and Crutches		✓	Boats
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the Openings		✓	Masts, Yards, &c.
Lower Deck Beams & Fastenings	✓	Ditto ditto at other places		✓	Sails
Planksheers	✓	Keelsons		✓	Anchors, No. of
Sheerstrakes	✓	Clamps and Shells		✓	Cables
Topsides	✓	Ceiling		✓	Hawsers and Warps
Wales	✓	Rudder		✓	Standing and Running Rigging
Plank (Bottom) and Counter	✓	Copper	✓	When put on 1872	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned, and coated with Paint and Sallow.  
 Is now in good, and efficient condition, and  
 in my opinion eligible to remain as classed.

Committee's Minute 14<sup>th</sup> Oct. 1873

Character assigned

100A1

J. J. Turroch

Certificate (if required).

No. 267 Survey held at London Date 26 Sep - 7 Oct 1873  
 on the General M<sup>r</sup> "Glenroy" Master J. J. Turroch  
 Tonnage 2122 Built at Glasgow When built 1871-10 mo  
 By whom built J. J. Turroch Owners A. C. Brown & Co  
 Port belonging to Glasgow Destined Voyage China  
 If Surveyed Afloat or in Dry Dock James Limited Dry Dock and Afloat

Last Survey, No. 9625 Port of Iron Classed 100A1

The present Condition of the

Decks	Good	Freecails	Ports	Good	Windlass and Cupstan
Waterways	✓	Breasthooks and Stenson		✓	Pumps
Comings	✓	Transoms, Pointers, and Crutches		✓	Boats
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the Openings		✓	Masts, Yards, &c.
Lower Deck Beams & Fastenings	✓	Ditto ditto at other places		✓	Sails
Planksheers	✓	Keelsons		✓	Anchors, No. of
Sheerstrakes	✓	Clamps and Shells		✓	Cables
Topsides	✓	Ceiling		✓	Hawsers and Warps
Wales	✓	Rudder		✓	Standing and Running Rigging
Plank (Bottom) and Counter	✓	Copper	✓	When put on 1871	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Bottom cleaned, and coated with Paint and Sallow.  
 Is now in good, and efficient condition, and in  
 my opinion eligible to remain as classed.

Committee's Minute 14<sup>th</sup> Oct. 1873

Character assigned

100A1

J. J. Turroch

Certificate (if required).