

ANNUAL SURVEYS.

33365

No. 413 Survey held at London Date 25th Feb^r 1873
 on the Iron Screw Steamer Shoreham Master C. June
 Tonnage 491³/₈ Built at Port Glasgow When built 1872 - 8 mo.
 By whom built Masfuden Owners S. Clarke & Co.
 Port belonging to London Destined Voyage Crossing
 If Surveyed Afloat or in Dry Dock Commercial dry dock

Last Survey, No. 11498 Port of Iron Classed 90. A. 1.

The present Condition of the

Decks	<u>good</u>	Ironails	<u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	"
Planksheers	"	Keelsons		"	Anchors, No. of	<u>3 B. 1 S. 2 K</u>
Sheerstrakes	"	Clamps and Shelves		"	Cables	"
Topsides	"	Ceiling		"	Hawsers and Warps	"
Wales	"	Rudder	<u>efficient</u>	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper		When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good
 Clean'd the bottom, and caulk'd the greater portion of the butts in the bottom (chiefly at the bilges) which bore the appearance of leakage. - recoated, or painted and put all in order, - I am of opinion she is entitled to remain as class'd

Committee's Minute 10th Oct^r 1873

Samuel Presons

Character assigned

90 A 1

IBW

Certificate (if required).

No. 220 Survey held at London Date Feb^r 25th 1873
 on the Iron Ship Ivanhoe Master Luke
 Tonnage 1383 Built at Port Glasgow When built 1868 - 10 mo.
 By whom built Reed Owners Williamson & Co.
 Port belonging to Liverpool Destined Voyage —
 If Surveyed Afloat or in Dry Dock Union dry dock

Last Survey, No. 16821 Port of Iron Classed A. 1.

S. S. no 1/72

The present Condition of the

Decks	<u>good</u>	Ironails	<u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places		"	Sails	"
Planksheers	"	Keelsons		"	Anchors, No. of	<u>3 B. 1 S. 2 K</u>
Sheerstrakes	"	Clamps and Shelves		"	Cables	"
Topsides	"	Ceiling		"	Hawsers and Warps	"
Wales	"	Rudder	<u>efficient</u>	"	Standing and Running Rigging	"
Plank (Bottom) and Counter	"	Copper		When put on		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good
 Clean'd and recoated the bottom. She is now in good condition and in my opinion is entitled to remain as class'd

Committee's Minute 10th Oct^r 1873

Samuel Presons

Character assigned

90 A 1

IBW

Certificate (if required).

Thoreau &
Wanhoe



© 2019

Lloyd's Register
Foundation