

ANNUAL SURVEYS.

33377

No. 399 Survey held at London Date 8th Decr 1873.
 on the *Mermaid* Master Geo. Lawrence
 Tonnage 1257 Built at Hull When built 1864-10 mo
 By whom built Earle Owners Hornsted & Co
 Port belonging to Liverpool Destined Voyage Aden
 If Surveyed Afloat or in Dry Dock In the Victoria Dock Tontoon and Afloat.

Last Survey, No. 10945		Port of Iron		Classed 1st	
The present Condition of the					
Decks	Good	Freeboards	Reels	Windlass and Capstan	Good
Waterways	Good	Breasthooks and Stenson		Pumps	
Comings	Good	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	Good	Timbers of the Frame at the Openings		Masts, Yards, &c.	Good and Sufficient
Lower Deck Beams & Fastenings	Good	Ditto ditto at other places		Sails	
Plank sheers	Good	Keelsons		Anchors, No. of 3 B. 15. 24	
Sheerstrakes	Good	Clamps and Shelves		Cables	Good
Topsides	Good	Ceiling		Hawsers and Warps	and
Wales	Good	Rudder		Standing and Running Rigging	Sufficient
Plank (Bottom) and Counter	Good	Copper	When put on		
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways					
Bottom cleaned and coated with Patent Composition Is now in good and efficient condition, and in my opinion eligible to remain as classed.					
Committee's Minute 14th Octr 1873		J. H. Burnes			
Character assigned A1		J. H. Burnes			
Certificate (if required).					

No. 456 Survey held at London Date 8th Decr 1873.
 on the *Mermaid* Master Geo. Lawrence
 Tonnage 2182 Built at Glasgow When built 1873 - 2 mo
 By whom built Thomson Owners J. Skinner & Co
 Port belonging to Glasgow Destined Voyage China
 If Surveyed Afloat or in Dry Dock Thames Limited Dry dock

Last Survey, No. 18073		Port of Iron		Classed 1st	
The present Condition of the					
Decks	Good	Freeboards	Reels	Windlass and Capstan	Good
Waterways	Good	Breasthooks and Stenson		Pumps	
Comings	Good	Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	Good	Timbers of the Frame at the Openings		Masts, Yards, &c.	Good and Sufficient
Lower Deck Beams & Fastenings	Good	Ditto ditto at other places		Sails	
Plank sheers	Good	Keelsons		Anchors, No. of 3 B. 15. 24	
Sheerstrakes	Good	Clamps and Shelves		Cables	Good
Topsides	Good	Ceiling		Hawsers and Warps	and
Wales	Good	Rudder		Standing and Running Rigging	Sufficient
Plank (Bottom) and Counter	Good	Copper	When put on 1873		
General Observations and Opinion, Caulking of Bottom, Deck, and Waterways					
Bottom cleaned, and coated with Paint. Is now in good and efficient condition and in my opinion eligible to remain as classed.					
Committee's Minute 14th Octr 1873		J. H. Burnes			
Character assigned 100A		J. H. Burnes			
Certificate (if required).					