

ANNUAL SURVEYS.

33364

182 No. 1093 Survey held at London Date 15th Sept. 1873.
 on the Ship Star of Persia Master Mr. Simpson
 Tonnage 1227 Built at Belfast When built 1868 6 mo
 By whom built Harland Owners Corry & Co
 Port belonging to Belfast Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Blackwall Port dry dock and afloat.

Last Survey, No. 1093		Port of Iron		Classed [*] Fall	
The present Condition of the					
Decks	Good	Precails	Rivets	Good	Windlass and Capstan
Waterways	—	Breasthooks and Stems	—	—	Pumps
Comings	—	Transoms, Pointers, and Crutches	—	—	Boats
Upper Deck Beams & Fastenings	—	Timbers of the Frame at the Openings	—	—	Masts, Yards, &c.
Lower Deck Beams & Fastenings	—	Ditto ditto at other places	—	—	Sails
Planksheers	—	Keelsons	—	—	Anchors, No. of
Sheerstrakes	—	Clamps and Shells	—	—	Cables
Topsides	—	Ceiling	—	—	Hawsers and Warps
Wales	—	Rudder	—	—	Standing and Running Rigging
Plank (Bottom) and Counter	—	Copper	Lead	When put on 1868	
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways			
Bottom cleaned and coated with M. Smith's Composition deck fittings repaired is now in good and efficient con- dition, and in my opinion eligible to remain as classed.					
Committee's Minute		10 th Oct.		1873	
Character assigned		* Fall		J. H. Warner	
		J. H. Warner		Certificate (if required).	

113 No. 10897 Survey held at London Date 1st October 1873.
 on the Ship Kingston Master Van Norden
 Tonnage 1208 Built at Hull When built 1864 4 mo
 By whom built Samuelson Owners Stuart & Co
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock R. H. Meens' Dry Dock and afloat

Last Survey, No. 10897		Port of Iron		Classed [*] Fall	
The present Condition of the					
Decks	Good	Precails	Rivets	Good	Windlass and Capstan
Waterways	—	Breasthooks and Stems	—	—	Pumps
Comings	—	Transoms, Pointers, and Crutches	—	—	Boats
Upper Deck Beams & Fastenings	—	Timbers of the Frame at the Openings	—	—	Masts, Yards, &c.
Lower Deck Beams & Fastenings	—	Ditto ditto at other places	—	—	Sails
Planksheers	—	Keelsons	—	—	Anchors, No. of
Sheerstrakes	—	Clamps and Shells	—	—	Cables
Topsides	—	Ceiling	—	—	Hawsers and Warps
Wales	—	Rudder	—	—	Standing and Running Rigging
Plank (Bottom) and Counter	—	Copper	Lead	When put on 1864	
General Observations and Opinion,		Caulking of Bottom, Deck, and Waterways			
Bottom cleaned and coated with Paint and Tallow is now in good and efficient condition and in my opinion eligible to remain as classed.					
Committee's Minute		10 th Oct.		1873	
Character assigned		* Fall		J. H. Warner	
		J. H. Warner		Certificate (if required).	