

See from No 10653 - Sept 72 11990

33283

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London Date, first Survey 29 July Last Survey 29 Aug 1873
on the Ship "Magpore" Master A. Kerellick
Tonnage 1198 built at Glasgow When built 1863-9 mo
By whom built Barclay Owners J. R. R. R.
Port belonging to Liverpool Destined Voyage India
If Surveyed Afloat or in Dry Dock On the Victoria Dock's Pontoon
Last Survey, No. 10653 Port London Classed *FA/1
REPAIRS, &c. (S.S. 1061-67, 9.72)

Chain cables ranged on deck for examination.
Bottom cleaned, and coated with Paint and
Sallow.

Present Condition of the

Decks	Good	Ironails	Rivets	Good	Windlass and Capstan	Good
Waterways	Good	Breasthooks and Stomson	Good	Pumps	Good	
Comings	Good	Transoms, Pointers, and Crutches	Good	Boats	Good	
Upper Deck Beams & Fastenings	Good	Timbers of the Frame at the openings	Good	Masts, Yards, &c.	Good	
Lower Deck Beams & Fastenings	Good	Ditto Ditto at other places	Good	Condition, how ascertained	Seen from the deck	
Planksheers	Good	Keelsons	Good	Sails	Good and sufficient	
Sheerstrakes	Good	Clamps and Shelves	Good	Anchors No. of	3 B 13. 2A	
Topsides	Good	Ceiling	Good	Cables	277 fms.	
Wales	Good	Rudder	Good	Hawsers and Warps	2 Good and	
Plank (Bottom) and Counter	Good	Copper sent. When put on	1863	Standing & Running Rigging	2 Sufficient	
Engine Room Skylights	Good	Caulking of	3 Good	Cargo and Main Hatchways	Good	
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	3 Good	Hatches	Good	
General Observations and Opinion,						

I am in good and efficient condition, and
in our opinion eligible to remain as classed.
By order S.S. No 2

The Amount of Entry Fee.....£..... is received by me,
Special.....2:2:.....
Certificate (if required) : 5: :
Committee's Minute 5th September 1873
Character assigned FA/1

180455-0297