

REPORT of SURVEY for REPAIRS.

Rev 24/11/73

No. in
Reg. Book.

No. 64

Survey held at

Shanghai

Date, first Survey

Sept

Last Survey

Sept 1873

on the

S.S. "Galley of Loni"

Master

Robertson

Tonnage

2147

built at

Glasgow

When built

1871-11 mo

By whom built

Napier

Owners

Shaw, Matton & Co

Port belonging to

London

Destined Voyage

Shanghai to Foochow

If Surveyed Afloat or in Dry Dock

dry dock

as per Run.
register Ton
out on Be
Engins Roo
Register To
Steamer, c

Length as

Survey, No.

96 96

Port

Shan

Classed

100 A.1.

REPAIRS, &c.

Keel, if
Do. if cen
Stem.
St

Vessel in dry dock. Bottom painted with
one coat. Decks recaulked all fore & aft

Present Condition of the

Decks

Good

Treenails

✓

Waterways

Good

Breasthooks and Stemson

Good

Comings

Good

Transoms, Pointers, and Crutches

Good

Upper Deck Beams & Fastenings

Good

Timbers of the Frame at the openings

✓

Lower Deck Beams & Fastenings

Good

Ditto Ditto at other places

✓

Planksheers

Good

Keelsons

Good

Sheerstrakes

Good

Clamps and Shelves

✓

Topsides

Good

Ceiling

Good

Wales

Good

Rudder

Good

Planks (Bottom) and Counter

Good

Copper

When put on

✓

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

General Observations and Opinion,

Windlass and Capstan

Good order

Pumps

Good order

Boats

Sufficient & Good

Masts, Yards, &c.

Good order

Condition, how ascertained

from deck

Sails

Sufficient

Anchors No. of

3 B 1 S 2 K

Cables

Not seen

Hawsers and Warps

Good & Sufficient

Standing & Running Rigging

Good order

Hatches

Good

Being now in good order and condition
consider eligible to remain as classed A.1. 100
at present. Ceu to Dec 72.

The Amount of Entry Fee.....£ 1 0 0 is received by me,

Special..... 3 16 0

Certificate (if required)

Committee's Minute 25th November 1873

Character assigned

100 A.1.



© 2019

Lloyd's Register
Foundation

120455-0381