

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 24057 Survey held at Liverpool Date, first Survey Dec<sup>r</sup> 13/73 Last Survey Jan<sup>r</sup> 6<sup>th</sup> 1874  
 on the Iron Ship "Dragon" Master M. Clemon  
 Tonnage 636 built at Stockton When built 1864-3 M<sup>o</sup>  
 By whom built Pearse Owners P. Harviside  
 Port belonging to London Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Canning Dry Dock and afloat.

Last Survey, No. 9818 Port Liverpool Classed \*A  
 REPAIRS, &c. now done. Bottom scraped and painted.

Rudder examined and pintles bushed. Ceiling lifted in flat of bottom, at least 6 strikes on both sides of keelson all fore & aft. for an examination of floors, frames, plates, Cement, &c., all of which now found in good condition. Repairs to Cement in places and floors Cement washed. Chain cables ramped on deck and found complete. Windlass unhooked and the wood lining striped and found in good condition.

## Present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>good and sufficient</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame at the openings <u>good</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings <u>good</u>	Ditto Ditto at other places <u>good</u>	Condition, how ascertained <u>seen on board</u>
Planksheers <u>good</u>	Keelsons <u>good</u>	Sails <u>good and complete</u>
Sheerstrakes <u>good</u>	Clamps and Shelves <u>good</u>	Anchors No. of <u>3 B. 1 S. 2 P.</u>
Topsides <u>good</u>	Ceiling <u>good</u>	Cables <u>good and complete</u>
Wales <u>good</u>	Rudder <u>good</u>	Hawsers and Warps <u>good</u>
Plank (Bottom) and Counter <u>painted</u>	Copper <u>Cement</u> When put on <u>1864</u>	Standing & Running Rigging <u>good</u>
Engine Room Skylights <u>good</u>	Caulking of <u>good</u>	Cargo and Main Hatchways <u>good</u>
Coal Bunker, Openings, Lids, &c. <u>good</u>	Bottom, Deck, & Waterways <u>good</u>	Hatches <u>good</u>
General Observations and Opinion, <u>This vessel is now in good condition and having undergone survey as required by the Rules is in my opinion eligible to remain as Classed *A and marked S.S. No 2 from this date.</u>	Scuppers <u>good</u>	

The Amount of Entry Fee.....£ - : - : - is received by me.

Special..... 3 : 3 : 0.

Certificate (if required) " : 5 : "

Committee's Minute Liverpool 13<sup>th</sup> January 1874

Character assigned \*A 1 - S.S. No 2 - 74



*Dragon 24057*



© 2019

Lloyd's Register  
Foundation