

ANNUAL SURVEYS.

No. 141 Survey held at London Date 10th Jan^y 1874
 on the Thos^{rs} "Farkle" (able) Master A Cooper
 Tonnage 1458 Built at London When built 1868 - 9 mo
 By whom built Green Owners W.H. Green & Co
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Same limited dry dock and afloat

Last Survey, No. 11200 Port of Crown Classed F.A. 1

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Freeboards

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where seen
 Caulked flat of upper deck. Bottom cleaned and coated with McInnis composition & now in good, and efficient condition. And in my opinion eligible to remain
 Committee's Minute 6th February 1874
 Character assigned F.A. 1 IBW W.H. Green Certificate (if required).

No. 24 Survey held at London Date 19th to 29th Jan^y 1874
 on the James "Vanessa" Master Martin
 Tonnage 1072 Built at Newcastle When built 1872. 2 mo.
 By whom built Palmer Owners Henry & Sons
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Victoria Dock, Port of London and Afloat

Last Survey, No. 10672 Port of Crown Classed 10A 1

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Freeboards

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Ditto ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

When put on

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors, No. of

Cables

Hawsers and Warps

Standing and Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Good where seen
 Bottom cleaned and coated with Paint & Tallow. & now in good, and efficient condition. and in my opinion eligible to remain as classed.
 Committee's Minute 6th February 1874
 Character assigned 10A 1 IBW W.H. Green Certificate (if required).