

# ANNUAL SURVEYS.

No. 141 Survey held at London Date 19 Jan 1874  
 on the Tenacious "Orchis" Master Lucas  
 Tonnage 1765 Built at Glasgow When built 1870-11 mo  
 By whom built Lamiae Owners Hargrove & Co  
 Port belonging to Liverpool Destined Voyage Europe  
 If Surveyed Afloat or in Dry Dock Frames limited dry dock and afloat

Last Survey, No. 11715 Port of Liver Classed 100 A1  
7.73

The present Condition of the

Decks	Pre-rails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Lead</u> When put on <u>1870</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Bottom cleaned and coated with Paint and a Fallom.  
Ship in good and efficient condition and  
in my opinion eligible to remain  
as classed.

Committee's Minute 6th February 1874

Character assigned 100 A1 R.W. H. Turner

Certificate (if required).

No. 67 Survey held at London Date 19 Jan 1874  
 on the Ship "Saint Monan" Master P. Dumaresq  
 Tonnage 1469 Built at Liverpool When built 1868-2 mo  
 By whom built Royden Owners Bankin & Co  
 Port belonging to Glasgow Destined Voyage India  
 If Surveyed Afloat or in Dry Dock R.H. keeps dry dock and afloat

Last Survey, No. 11238 Port of Liver Classed 100 A1  
4.73

The present Condition of the

Decks	Pre-rails <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Lead</u> When put on <u>1868</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good where examined

Bottom cleaned and coated with patent composition.  
Ship in good and efficient condition and in  
my opinion, eligible to remain as classed.

Committee's Minute 6th February 1874

Character assigned 100 A1 R.W. H. Turner

Certificate (if required).