

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **386** No. **12347** Survey held at **London** Date, first Survey **26 Jan** Last Survey **1874**  
 on the **Barb. Hoshu Castle** Master **James Alexander**  
 Tonnage **644** built at **Glasgow** When built **1863 - S.M.**  
 By whom built **Bunnell** Owners **Skinner & Co**  
 Port belonging to **Glasgow** Destined Voyage **Auckland**  
 If Surveyed Afloat or in Dry Dock **At H. Meens Dry Dock and Afloat**

Last Survey, No. **9671** Port **Iron** Classed **\*FA/1**

## REPAIRS, &c.

Now done to complete the S. S. No 23 Tide Gauge Report No. 9671 -

All the close-ceiling in the hold from the middle line to the upper turn of bilge, on each side, extending from the aft side of the fore-rigging to the aft side of main rigging, removed; the parts where so exposed have been cleaned and washed with cement; and the thick cement coating repaired. Frames and plating from turn of bilge to hold beam stringer cleaned and painted all fore and aft on each side. The ceiling where removed for

## Present Condition of the

Decks	Ironails	Rivets	Wood	Windlass and Capstan
Waterways	Breasthooks and Stemson			Pumps
Comings	Transoms, Pointers, and Crutches			Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings			Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places			Condition, how ascertained
Planksheers	Keelsons			Sails
Sheerstrakes	Clamps and Shelves			Anchors No. of
Topsides	Ceiling			Cables
Wales	Rudder			Hawsers and Warps
Plank (Bottom) and Counter	Copper	When put on		Standing & Running Rigging
Engine Room Skylights	Caulking of			Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways			Hatches
General Observations and Opinion	Scuppers			

Now in good and efficient condition and in my opinion eligible to remain as classed and be marked (S. S. No 2-74)

The Amount of Entry Fee.....£..... is received by me,

Special.....£.....

Certificate (if required).....£.....

Committee's Minute **24<sup>th</sup> February 1874**

Character assigned **\*FA/1**

S. S. No 2-74

*[Signature]*

*[Signature]*

*[Signature]*



© 2019  
 Lloyd's Register  
 Foundation  
 R0N456-0246

12347 Iron  
Survey has been renewed of Pine <sup>in</sup>  $\frac{1}{2}$  thick,  
the plat, laid in hatches.

# Bottom cleaned and coated with  
patent composition.

W. H. Turner



© 2019

Lloyd's Register  
Foundation