

ANNUAL SURVEYS.

33626

12350

Recd 9.2.74

No. 153 Survey held at London Date 31st Jan^y 18 74
 on the Iron Ship Weymouth Master Hunt
 Tonnage 830 Built at P. Glasgow When built 1858
 By whom built Reid Owners Temperley
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Blackwall Point dry dock

Last Survey, No. 11006 Port of Iron (U.S. Low No 3.71) Classed *A1 133

The present Condition of the

Decks	Freemasts <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> 1858 <u>1871</u>	

Good where seen *Good where seen* *Good and sufficient*

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Rudder pintles repaired the bottom cleaned and coated with patent composition

Is now in good and efficient condition and eligible to remain as classed

Committee's Minute 13th February 1874

Character assigned

*A1
L.P.

J.W. Blaxell Certificate (if required).

No. 153 Survey held at London Date 30th Jan^y 18 74
 on the Iron Screw Steamer Lord of the Isles Master Sowdy
 Tonnage 1846 Built at Glasgow When built 1870 - 6 mo
 By whom built Napier Owners Shaw Manton & Co.
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock Thames Limited dry dock

Last Survey, No. 100A1 Port of 100A1 Classed 100A1 872

The present Condition of the

Decks	Freemasts <u>Rivets</u>	Windlass and Capstan
Waterways	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper <u>Cement</u> When put on <u>1870</u>	

Good where seen *Good where seen* *Good and sufficient*

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Cement in way of timbers in good condition and firmly adhering to iron the bottom cleaned and coated with paint and Tallow

Committee's Minute 13th February 1874

Character assigned

100A1
L.P.

Is now in good and efficient condition and eligible to remain as classed

J.W. Blaxell Certificate (if required).