

ANNUAL SURVEYS.

Rec 6/4/76

No. 2244 Survey held at Belfast Date 23rd March 1874
 on the S.S. Camel Master J. J. Patten
 Tonnage 323 Built at Cupar When built 1870 Mo 9
 By whom built Harland & Wolff Owners Harland & Wolff
 Port belonging to Cupar Destined Voyage Coaster
 If Surveyed Afloat or in Dry Dock In patent slip and afloat

Last Survey, No. 11595 Port of Belfast Iron Classed 100 A. 1.

The present Condition of the

Decks <u>Good</u>	Freemasts <u>When seen good</u>	Windlass and Capstan
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>do</u>	Sails
Plank sheers <u>do</u>	Keelsons <u>do</u>	Anchors, No. of
Sheerstrakes <u>do</u>	Clamps and Shells <u>do</u>	Cables
Topsides <u>do</u>	Ceiling <u>do</u>	Hawsers and Warps
Wales <u>do</u>	Rudder <u>do</u>	Standing and Running Rigging
Plank (Bottom) and Counter <u>do</u>	Copper <u>do</u> When put on <u>do</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Not done. Bottom cleaned down and coated with black varnish and paint; inside iron work painted. Is in good and efficient condition, and eligible to remain as classed

Committee's Minute 7th April 1874

Character assigned 100 A

J. B. W. S. J. McNeill

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Plank sheers	Keelsons	Anchors, No. of
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing and Running Rigging
Plank (Bottom) and Counter	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute _____ 18____

Character assigned _____



© 2019

Certificate (if required).

Lloyd's Register Foundation