

ANNUAL SURVEYS.

Rev 2/4/74

No 402
in Register
No 602

No. 3282 Survey held at West Hartlepool Date 23rd March 1874
on the S.S. "Mary" Master H. Lawson
Tonnage 840 Built at West Hartlepool When built 1871 - 4 mo
By whom built Denton Owners Johnston & Sons
Port belonging to Montrose Destined Voyage Baltic
If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 11625 Port of Iron Classed 90 A1

The present Condition of the

Decks Good
Waterways (Gullies) Good
Comings Good
Upper Deck Beams & Fastenings Good
Lower Deck Beams & Fastenings Good
Plank-sheers Good
Sheerstrakes Good
Topsides Good
Wales Good
Plates Good
Plank (Bottom) and Counter Good

Treenails Good
Breasthooks and Stems Good
Transoms, Pointers, and Crutches Good
Timbers of the Frame at the Openings Good
Ditto ditto at other places Good
Keelsons Good
Clamps and Shells Good
Ceiling Good
Rudder Good
Copper Good When put on Good

Windlass and Capstan Good
Pumps Two & Good
Boats Four & Good
Masts, Yards, &c. Good
Sails Good
Anchors, No. of 3 Bowers / Steam 2 / Redg
Cables 1 7/16 Good
Hawsers and Warps 9-7 1/2 - 7-6 1/2 - 5 1/2 Good
Standing and Running Rigging Good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Now done, bottom cleaned down & coated with paint & black varnish.
Is now in a good & efficient state, fit for the safe conveyance of dry &
perishable goods to & from all parts of the World & may in my opinion remain
as now Classed 90 A1

Committee's Minute 18

Character assigned

90 A1

J. P. Gladstone

Certificate (if required).

No. 3283 Survey held at West Hartlepool Date 26th March 1874
on the S.S. "Schway" Master Thos. Whiteman
Tonnage 792 1/2 Built at Hartlepool When built 1873 - 6 mo
By whom built Witby Owners G. Steed & Co
Port belonging to West Hartlepool Destined Voyage Mediterranean
If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 11638 Port of Iron Classed 90 A1

The present Condition of the

Decks Good
Waterways (Gullies) Good
Comings Good
Upper Deck Beams & Fastenings Good
Lower Deck Beams & Fastenings Good
Plank-sheers Good
Sheerstrakes Good
Topsides Good
Wales Good
Plates Good
Plank (Bottom) and Counter Good

Treenails Good
Breasthooks and Stems Good
Transoms, Pointers, and Crutches Good
Timbers of the Frame at the Openings Good
Ditto ditto at other places Good
Keelsons Good
Clamps and Shells Good
Ceiling Good
Rudder Good
Copper Good When put on Good

Windlass and Capstan Good
Pumps Two & Good
Boats Three & Good
Masts, Yards, &c. Good
Sails Good
Anchors, No. of 3 Bowers / Steam 2 / Redg
Cables Good
Hawsers and Warps 8 1/2 - 7 1/4 - 6 1/4 - 5 - 4 1/2 Good
Standing and Running Rigging Good

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Now done, bottom cleaned down & coated with paint & black varnish. inside
with paint. Is now in a good & efficient state fit for the safe conveyance of
dry & perishable goods to & from all parts of the World & may in my opinion remain
as now Classed 90 A1

Committee's Minute 18

Character assigned

90 A1

J. P. Gladstone

Certificate (if required).