

ANNUAL SURVEYS.

Rev 18/4/74

No. 129 Survey held at Newcastle Date 26th February 18 74
 on the S.S. Mercury Master Bethell
 Tonnage 839 Built at Newcastle When built 1864 - 2 mo
 By whom built Palmer Owners Palmer & Co
 Port belonging to Newcastle Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Palmer dry dock

Last Survey, No. 10250 Port of Lyon Classed A 1
5.72
 S.S. Brs. No 3-72

The present Condition of the

Decks <u>Good</u>	Timbers <u>Ribs</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	<u>Framing</u> <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	<u>Ditto ditto at other places</u>	Anchors, No. of <u>3 13 15 2 K</u>
Sheerstrakes <u>"</u>	Keelsons <u>"</u>	Cables <u>Sufficient</u>
Topsides <u>"</u>	<u>Clamps and Shells</u> <u>Springer</u> <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Ceiling <u>"</u>	Standing and Running Rigging <u>Good</u>
Plank (Bottom) and Counter <u>"</u>	Rudder <u>"</u>	
	Copper <u>"</u> When put on <u>"</u>	


General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

This vessel having been scraped & coated & being in good condition. I am of opinion she is fit to remain as classed A 1

Committee's Minute 14th April 18 74

Character assigned A 1

Geo. T. Cooper


Certificate (if required).

No. _____ Survey held at _____ Date _____ 18 ____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Sails _____
Planksheers _____	Keelsons _____	Anchors, No. of _____
Sheerstrakes _____	Clamps and Shells _____	Cables _____
Topsides _____	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder _____	Standing and Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18 ____

Character assigned _____



© 2019

Lloyd's Register
 Foundation