

ANNUAL SURVEYS.

No. in Reg
Bt 218

Rec 21/5/74
No. 4279 Survey held at Hull Date 4th May 1874
on the Iron Schooner St. Antonio Master Jo. Oliveira
Tonnage 1441 Built at Glasgow When built 1860-1861
By whom built Hill Owners Bailey & Co
Port belonging to Lisbon Destined Voyage Lisbon
If Surveyed Afloat or in Dry Dock On Mumps & Hausers No. 2 Slip-way

Last Survey, No. 12124 Port of Iron Classed 100 A 1
SS Hull No. 170 11.73

The present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>Good</u>	Breasthooks and Stemson	<u>Good</u>	Pumps	<u>Good</u>
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	<u>Good</u>	Boats	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the Openings	<u>Good</u>	Masts, Yards, &c.	<u>Good</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto ditto at other places	<u>Good</u>	Sails	<u>Good</u>
Planksheers	<u>Good</u>	Keelsons	<u>Good</u>	Anchors No. of	<u>Good</u>
Sheerstrakes	<u>Good</u>	Clamps and Shelves	<u>Good</u>	Cables	<u>Good</u>
Topsides	<u>Good</u>	Ceiling	<u>Good</u>	Hawsers and Warps	<u>Good</u>
Wales	<u>Good</u>	Rudder	<u>Good</u>	Standing & Running Rigging	<u>Good</u>
Plank (Bottom) and Counter	<u>Good</u>	Copper	<u>Good</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

Now done - Bottom cleaned & painted
Is in good condition and eligible in my opinion to remain as Classed A 1

Committee's Minute 22nd May 1874

Character assigned 100 A 1

J. Davidson

Certificate (if required).

No. _____ Survey held at _____ Date _____ 18____
on the _____ Master _____
Tonnage _____ Built at _____ When built _____
By whom built _____ Owners _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____



© 2019

Lloyd's Register
Foundation

Certificate (if required).

IRON 457-0214