

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.

No. 383

Survey held at Glasgow

Date, first Survey 30th AprilLast Survey 14th May 1874

on the Tarn Ship Glenecoe

Master Wm Palmer

Tonnage 727

built at Dumbarton

When built 1855

By whom built Denny & Munro

Owners H Martini

Port belonging to Glasgow

Destined Voyage Glas. San Francisco

If Surveyed Afloat or in Dry Dock

Mps Barclay, Clark & Co Ship and Afloat

Last Survey, No. 11389

Port Glasgow

Classed A1

REPAIRS, &c.

SB ch 1873-5-73

The Rudder and its braces renewed. Waterways caulked and the wood hullwork stenciled. Stays washed in. The bottom scraped and recoated. The masts and spars overhauled and refitted.

Present Condition of the

Decks	Good	Treenails	Good	Windlass and Capstan	Good
Waterways	✓	Breasthooks and Stemson	✓	Pumps	✓
Comings	✓	Transoms, Pointers, and Crutches	✓	Boats	✓
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the openings	✓	Masts, Yards, &c.	✓
Lower Deck Beams & Fastenings	✓	Ditto Ditto at other places	✓	Condition, how ascertained	From the deck
Planksheers	✓	Keelsons	✓	Sails	Said to be complete
Sheerstrakes	✓	Clamps and Shelves	✓	Anchors	No. of 33 18 M
Topsides	✓	Ceiling	✓	Cables	Said to be complete
Wales	✓	Rudder	Good	Hawsers and Warps	✓
Plank (Bottom) and Counter	✓	Copper	Good	Standing & Running Rigging	✓
Engine Room Skylights	✓	When put on	1855		
Coal Bunker	✓	Caulking of	✓		
Openings, Lids, &c.	✓	Bottom, Deck, & Waterways	Good		
Scuppers	Good				
Cargo and Main Hatchways	Good				
Hatches	Good				

General Observations and Opinion,

This vessel is now in good and efficient condition. Eligible to remain as classed A1

The Amount of Entry Fee.....£ : : : is received by me,

Special..... / : / : "

Certificate (if required) " : " : "

Committee's Minute

29th May 1874

Character assigned

J.B.W.



© 2019

Lloyd's Register
Foundation